) uglity (
Control
Stage: Before St
epot.
Stage:
Before
Stage: Before Casting Slab (Villas
Slab (Villas
illa

Recommendation: Stop further work. Stop further work Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.		no. 3/060		Signal Limbin	AAH	67
QC team. P. mitting ATR rections poi	MD Sign	So	Sign	Sign	Project	Slab No.
oceed only after recheck by Con QC report to QC team. Ited out in the QC report. ATI		Report filed and signed by PM?	- Coppor		AVR GILLMO-hus	01
QC.	For filling	M?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	KYes □No	95/06/19	25/06/19		33865

Slab Check. Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.

 Prepare Slab Dimensions Check Plan as follows:

 a. Show outer dimensions of slab. (Tolerance 2")

 b. Show length and width of balconies (Tolerance 1")

 c. Show inner dimensions of ducts. (Tolerance 1")

 d. Show location of sunken slab.

 e. Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

4. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.	n colour. Circle each incorrect of	dimension with red colour and	mention actual dimension next to	ĮF.
Slab Dimensions Check Plan enclosed?	d?	⊠Yes □No		
Staircase - mid landing1	Specified ht: A g	4.9 Actual ht: 4.911	A) gil Within tolerance of 1/2"? Yes \(\text{No}\)	Yes No
Staircase - mid landing 2	Specified ht:	Actual ht:	Within tolerance of ½"?	☐ Yes ☐ No
Staircase width	Specified wd:	Actual wd:	Within tolerance of ½"? ✓ Yes ☐ No	Yes UNo
Staircase slab thickness	Specified:	Actual: A	Within tolerance of 1/4"?	Yes No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good Avg. Bad
18"extension to beam bottom runners on outer side provided?	□Yes □No
Quality of Bracing Provided?	☐ Good ☑ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good ☐ Avg. ☐ Bad
Shuttering leveling?	Good Avg. Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks:	
THE PROPERTY OF THE PROPERTY O	

Slab Steel check. Notes:

- Mark

 for correct or minor mistake which does not require correction
 Mark

 for minor mistake that requires minor correction.
 Mark

 for major mistake that requires correction by replacement or re-fixing.
 Mark

 K

 for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:
Good Avg. Bad		Steel check – slab extensions/ joints	16.
☐ Good ☐ Avg. ☐ Bad	Ĵ	Steel check – floating columns	15.
Good Avg. Bad	<	Electrical Conducting	14.
☐ Good ☐ Avg. ☐ Bad	<	Steel Check - Column steel overlapping length and cranking	13.
☐ Good ☐ Avg. ☐ Bad		Covering blocks for slab	12.
☐ Good ☐ Avg. ☐ Bad		Steel Check - Slab Extra Bars	11.
☐ Good ☑ Avg. ☐ Bad		Steel Check - Slab cranking & chairs	10.
Good ☐ Avg. ☐ Bad	7	Steel Check - Slab spacing of bars	9.
Good Avg. Bad	ζ	Steel Check - Slab size of bars	8.
☐ Good ☐ Avg. ☐ Bad	<	Depth and width of beams	7.
☐ Good ☐ Avg. ☐ Bad		Covering blocks for beams	6.
☐ Good ☐ Avg. ☐ Bad		Steel Check - Beams Bearing	5.
Good Avg. Bad		Steel Check - Beams Overlapping & Cranking	4.
☐ Good ☐Avg. ☐ Bad	<	Steel Check - Beams Extra Bars	ω
Good Avg. Bad	(Steel Check - Beam size of bars	2.
Good Avg. Bad		Steel Check - Beam no of rods	
Qualitative Check (Good / Avg. / Bad)	Quantitative Check	Item	S No