Quality Control Check Repot. Stage: Before Casting Footings (Villas)

	4 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7			Remarks:
	☐ Good ☐ Avg. ☐ Bad		or curing.	Quality of infrastructure for curing
	Exes No	end?	ng pipe more than 15' h	Is the pressure in the curing pipe more than 15' head?
	2 Jumes	quire from labourers)	mber of times a day (cr	Frequency of curing in number of times a day (enquire from labourers)
OHT Bore-well direct connection	Sump OHT Bore-we		9	Source of water
	10-0	Distance of tap from furthest distance that requires curing. (max permitted 100')	nest distance that requir	Distance of tap from furth
	Yes No	The second secon	t for curing.	Tap provide at Apartment for curing
				Curing.
Ved.	should be removed	OB FOOTINGS MIN	e Costiny	The fore
Good Maye. Bad	Good		bending and marking?	Quality of centering, rod bending and marking?
			bending and marking.	Quality of centering, rod bending and marking
	report. ATR not required.	Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	Proceed with further work only after making Proceed with further work. ATR not required	Proceed with further Proceed with further
	recheck by QC.)C team.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.	ibmit ATR on QC report roceed with work after to	Stop further work. Stop further work. P
				Recommendation:
Yes No	For Filing)1)	Sign	Approved by MD Date
10-4-18	Date	in .	r. 1	Project Manager
01478	Date		S-Syn Jum Sign	Prepared by
	Morton Phase	Project AVR- Gullor	Abit Pr	Company
いの十分で	SI. No.	Other	0 S.E.	Block No.

Quality Control Check Repot. Stage: Before Casting Footings (Villas)

Specified size of covering blocks Remarks:	COMM	Actual size of covering blocks being used	Somo
Earth Work Check.			
Quality of earth work?	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐Avg. ☐ Bad Excess earth shifted away from site?	☐ Yes ☐No
Remarks:			

Footings Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing. Mark XXX for major mistake that cannot be corrected.
- Pit size should be 6" to 12" more than the footings size on all sides.
- Excess earth must be shifted away from footings area.

 Depth should be more than or equal to the specified depth. Keep in mind PCC thickness & sand filling wrt to road FFL.
- PCC should be 3"more than the footing size (or as specified) and in one level. (Level tolerance 1")
- Footing size & depth tolerance is 1". Depth of footing must be marked by paint on column steel.
- 10. Proper pegs must be made for centerline marking on all sides in CRS or brickwork. Marking with rods is not permitted.
- 11. If space between footings is less than 12"then a 4"hollow block wall with mortar is to be raised between the footings. Do not combine the footings.
- 12. Covering blocks of specified thickness must be used (generally 50 mm). Tolerance 1/4".
- 13. Cheek the specified development lengths for mat and columns.

Quality Control Check Repot. Stage: Before Casting Footings (Villas)

		_					8		Γ	Γ	T			_	_	T-		Т	T	7		-	т
23.	22.	21.	20.	19.	.≅	17.	16.	15.	14.	13.		5 1	; = , ,	5 :	ه م	× .	J 0.	٠	4.	ا د	2.	· -	S no
					!		_				G5	Gia	1.5	F3	E1	S	C3	Cr	BB	25	A3	A1	Col No
											CA	C	Ca	Ca	5	5	Ca	C	Ca	Ca	Ca	Ca	Col type
		_								410	<	ζ	<	k	<	<	<	۲	5	ς	ς	5	Pit size
											(1	((7	7	ζ	(?	ζ	7	?	Pit
			-								٢	<	<	5	?	7	5	ς	7	ζ	ς	ς	PCC level
											ζ_	ζ	(<	<	ς	(ζ	<	<	ζ	۲	Footing size
											(ζ	ζ.	C	7	((ς.	((ζ.	~	Pooting depth marking
											۲	(<	ς	۲	<	ς	۲	ς	(٢	(Mat size
											ς	ζ	ζ	((((٢	(۲	٢	۲	Mat steel
											7	*	((7	(۲	(٢	ζ.	((Column steel
											5	ζ	ζ	ζ.	ζ	ζ	ς,	ζ,	\	ζ.	ζ	5	Development lengths for mat & columns
		<u> </u>							-		1	1	}	١)	1	1)	1	1	1	Pegs for centre- line
												1	7	(?	((7	((()	?	Spacing between footings

Page 3 of 3