Recommendation: Checked By MD on Previous stage report no Project Manager Prepared by Company Block No Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Quality Control Check Repot. Kadhestram | Sign I lam extrate 2 - 08 3225 MD Sign Sign Project Stage: Before Casting Plinth Beam (Villas) Report filed and signed by PM? 12/21 For filling Date Date Phase Sl. No. Ş カーカーカ _ Yes [] Yes カニカ 区公 No 1 N S

Plinth Beam Check

- Prepare plinth beam Dimensions Check Plan as follows: Inspection should be done before casting of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
- Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Plinth Beam Dimensions Check Plan enclosed?
□YYes □ No

, , Quality Control Check Repot. Stage: Before Casting Plinth Be

nth Beam Steel check,	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D) Correct Needs correction			Have rods for staircase slab been provided? Good Avg. Bad Quality of Bracing Provided?	Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting?
	correction	Bad	Bad	Bad	

Plin

Mark of for correct or minor mistake which does not require correction Mark for minor mistake that requires minor correction.

Mark x for major mistake that requires correction by replacement or re-fixing. Mark x for major mistake that cannot be corrected.

Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	Remarks:	7.	6.	5.	4.	3,	2.	1.	s No
	The annual content of the Content of	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
					<		1		Quantitative Check
	•	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	<.	☐Good ☐Avg. ☐Bad	☐ Good [√Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	□,Good ¬Avg. □ Bad	Qualitative Check (Good / Avg. / Bad)