Quality (
Control Check Re
heck Repot.
S
Casting (
(villas)

Block No.	S Column No.	<u>o</u>	SI. No.	31176
Company A	AG.H Project	AVR Gulnichan	Phase	
Prepared by V.Sa	V. Sankith Sign	V. Suket	Date	16-08-18
Project Manager 7	Sign Sign	Falcer	Date	16-08-18
Previous stage report no.	34018	Report filed and signed by	d by PM?	Yes No
Checked By MD on	MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after su Proceed with further work only after making of the proceed with further work. ATR not required.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required Proceed with further work. ATR not required.	oceed only after recheck ton QC report to QC team.	by QC. ATR not required.	

Columns Position Check.

Notes:

- 1. Inspection should be done after casting of columns at each stage and before starting centering works for each slab
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20°, of bays. (Tolerance 1.5")
- Print an A3 size plan.

	Columns Position Check Plan enclosed?	Circle each correct dimension with green colour. Circle each incorrect dimension
	√ Ycs	n incorrect dimension/with red colour and mention actual dimension next to it.
1		ļ

Slab Dimensions Check.

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
 a Show outer dimensions of slab (Tolerance 2")
- Show inner dimensions of ducts and lift well. (Tolerance I") Show length and width of balconies (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Uncle each correct dimension with green colour. Uncle each incorrect dimension with red colour and mention actual dimension next to it

Specified thickness of slab?	Slab Dimensions Cheek Plan enclosed?	Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention
Actual thickness of slab?	Tes No	aclua
		n actual dimension next to it.

Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good Avg. Bad
Quality of starters?	☐ Good 🖾 Avg. ☐ Bad
Number and size of honey combs?	☐ High ☑ Medium. ☐ Low
Are the honey combs is slab and columns packed?	☐ Good 🗹 Avg. [☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	State of the state
Have 6 cubes each for columns and slab casted and numbered for testing?	√Yes □ No
Remarks:	
	The state of the s
Curing	
Bunds for curing made on slab? ☐ Yes ☐ No	
Bund size is less than 100 sft?	4
Drum (200 lts) provided for curing?	
Gunny bags used for column curing?	
Distance of tap from furthest distance that requires curing. (max permitted 100') 50	
Frequency of curing in number of times a day (enquire from labourers)	Companies de Amelier III de Marie de Ma
Is the pressure in the curing pipe more than 15' head?	
Quality of infrastructure for curing.	Bad
Remarks:	

Columns height, plumb, steel & level marking check.

Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25".
 Circle actual height of columns if level differs from specified height by more than 1".

Yes No		1								20.
Yes No		† - ·								19.
		† 								18.
] [† - · - ·								17.
		† · · · · · · · · · · · · · · · · · · ·								16.
							ļ	_(ני	15
	~	~	۷	۷	۷	8-6"	11-18	*	DF 1	14
1	2	2		<	4	8-51	17.8	S	7 .	15.
1	4	۷	۷,	2	4	1,9/2-18	11-18	S-	οG	12.
	~	۷.	4	۷.	7	8-8"	8-7"	7	۲ م	11.
	4	V	<u>\</u>	۷	حر	8-62"	114-18	(0)	61	10.
	۷.	۷,	۲,	~	۷,	11-19	114-18	60	S -	9.
	4	V_	4	~	<	1,7518	1,4-18	C 2	6	œ
	<	۲.		~	~	14/2	" F-8	6	22	7
	4	<	۲	~	۲	Staios	d sign	()	3/1	6.
1	4	۷	~	۷	4	Etaiss		Ć,	Ba	5.
	2	4	٧	<	ح	8-3"	14-1	C ₁	8.5	4.
	4	۷,	<	<	۷,	9'-6"	11 (-18	C),	D 1 U	'n
	~	Ž	۷	<u> </u>	۷,	8-5"	1, t, 8		P.	5
	4	<	۷.	<u> </u>	√	8-6"	"F-'8	r	D	1.
column?				rods	rods					•
marked on	Side 2	Side 1		Size of	No of	Actual	Spec.			
Reference level	Plumb (✓ or ×)	Plumb	Honeycombs	Steel (v or x)	Steel (Height in ft	Heigh	Col type	Col No.	SNo
ח_6		2	**	Or of contents	a mergen of a	Tom specimen	t Hele actual neight of commiss it teach of their about a promount neight of more man.	or commune it	actual incigin	o. Cher