Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required	Checked By MD on MD Sign For fill	Previous stage report no. 32807 Report filed and signed by PM?	Project Manager A. SURES IA Sign Date	Prepared by C. RAJESH Sign Date	Company VOC LLP Project VOC Phase	83 Stage S	
ck by QC. am. rt. ATR not required.	For filling	gned by PM?	Date	Date	Phase	SI, No.	
	□Yes □No	LYes □No	20/u/19	20/4/19		33437	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check,

Notes:

- Mark \checkmark for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18	17	16	15	14	13	12	11	10	9	∞	7	6	Ŋ	4	w	2	_	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony-2	Ferrace / balcony 1	Lebby 2	Lobby I Family Louge	Dining	Drawing	Toilet 4	4	2.7	Bedroom 3 M. Bed		n 2		Bedroom 1 M.Bed	Room
		1	<	1	<	3	<	4	<	\	/	1	,	7	Υ.	<	5	<	/	Skirting Provision (v or x)
		}	<		<	١	<	3	<	7	<	1	1	<	<	<	<	\	1	Finishing around doc frame (v or x)
		١	<	١	<	١	<	}	<	<	<	,1		<	<	<	<	<	1	Beams & columns finishing (• or ×)
		١	1	l	1)	١	1	١	1	Ì	1	١	١	١)	l	1	Finishing of lofts (v or X)
		}	<		<	١	<	ì		<	<	ı	١	\	<	<	1	<	7	Electrical junctions finishing (• or ×)
		١	<	١	1	١	1	1	<	5	<	1	1	<	\	\	7		<	Window check (v or x)
)	<	1	1	1	1	1	ſ	1)	1	1	<	1	<	1	7	4	Tiles provision (v or x)
		1	١	•	١	1)	ı	1	1	1		1	1	ľ	1	1	1)	Sink provision & size (v or x)
		1	<	1	X	١	\	1	*	7	*	1	1	7	X	<	ζ.	\	>>	Grooves for door frames (v or x)
		١	1	٩	1	1		1	1))			١	١))	1	}	Balcony & terrace sill top finishing 10(• or ×
)	-	1	1		1	Ì	I	1	1	ł		<	1	<	3		1	Screeding in bathroon & utility (• or ×)
		!	1)	1	1	1	8	1	1	١)		<	1	<	1	\	1	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

Remarks:	Plastering and finishing of chajjas (✓ or 🗙)	Plastering quality of parapet walls (✓ or ×)	Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Plastering of compound wall & gate pillars (• or ×)	Overall quality of plastering?	Miscellaneous check
	_	\	☐Yes ☐No	7	Good Avg. Bad	