Quality Control Check Repot. 'Stage: After Plastering (Villas)

Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR proceed with further work. ATR not required.	Checked By MD on	rievious stage report no.	r roject ivianager	Draint Man	Company	Villa No.
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR no Proceed with further work. ATR not required.		10.	· Purshotlar	a. RAJESH,	SOV (LLP)	æ
port to QC team. Proce er submitting ATR on on ng corrections pointed red.	MD Sign	34.061	Sign	Sign	Project	Stage
ed only after recheck by QC report to QC team. Out in the QC report. 1		Report filed and signed by PM?		an a	So 4	,
y QC. \TR not required.	For filling	d by PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	Yes No	04/20/10	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	(X	242

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark for correct or minor mistake which does not require correction

 Mark × for minor mistake that requires minor correction.

 Mark × for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ½".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
- Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Page 2 of

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good ☑ Avg. ☐ Bad "
Plastering of compound wall & gate billars (v or x)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	☐Yes ☐No
Plastering quality of parapet walls (• or *)	ζ.
Plastering and finishing of chajjas (✓ or 🗙)	<u> </u>
Remarks:	