Block No	4	1		SI. No.	81302
Company	AGH	Project	AVR Gulmbhar Phase	Phase	-
Prepared by	S. Kulderp	Sign	Delders	Date	29/09/2018
Project Manager	Zaků Hossain	Sign	Travel	Date	3195 80 102
Previous stage report no.		30862	Report filed and signed by PM?	ed by PM?	☐Yes ☐No
Checked By MD on	MD Sign	ign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck l Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	OC team. Proc mitting ATR or rrections pointe	eed only after recheck QC report to QC team d out in the QC report.	by QC. ATR not required.	

Quality Control Check Repot.

Stage: Before Casting Plinth Beam (Villas)

Plinth Beam Check.

- Inspection should be done before casting of plinth beam
 Yellow enamel paint to be used for marking FEL of flooring. Mark 2° above FFL on column steel. Plinth beam top must be 2°3° (in case of pavers) or 2°4" (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

 c. Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red reloar and mention actual dimension next to it

Yes \(\textstyle \tex	Plinth Beam Dimensions Check Plan enclosed?
--	---

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Plinth Beam Steel check.

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X X for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	ņ	2.	-	SNo	
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item	
	(<	<	(<	<	< \	Quantitative Check (• or ×)	
	Good Avg. Bad	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good Avg. ☐ Bad	✓Good Avg. Bad	☐Good ☐ Avg. ☐ Bad	☐Good ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)	