Recommendation: Checked By MD on Previous stage report no. Project Manager Prepared by Company Block No Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Proceed with further work. ATR not required. Proceed with further work only after making corrections pointed out in the QC report. ATR not required Stop further work. Proceed with work after submitting ATR on QC report to QC team. K. Purshalham (277) NBS 88 Sign 32457 Sign MD Sign Slab No. Project Report filed and signed by PM? 4. Buter Sax 9 Sl. No. Date For filling Date Phase VYes [ 17/01/19 17/01/19 Yes 32669 No No

Quality Control Check Repot.

Stage: Before Casting Slab (Villas)

## Slab Check.

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting
- Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with red colour and mention actual dimension.

Slab Dimensions Check Plan cnclosed?	d?		✓ Yes □ No	No		
Staircase - mid landing1	Specified ht: 41-5"	4-5-11	Actual ht: 415"	4-5"	Within tolerance of ½"?	✓ Yes ☐ No
Staircase - mid landing 2	Specified ht:	E-wat-	Actual ht:	•	Within tolerance of ½"?	☐Yes ☐No
Staircase width	Specified wd: $6 - 0 \frac{1}{2}$ Actual wd: $6 - 10$	5-01/2"	Actual wd:	621111	Within tolerance of ½"?	✓ Ycs ☐ No
Staircase slab thickness	Specified:	2 <sup>-</sup>	5" Actual:	ง	Within tolerance of ¼"? ✓Yes ☐ No	✓Yes □No

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good Avg. Bad
18"extension to beam bottom runners on outer side provided?	∏Yes √No
Quality of Bracing Provided?	Good Avg. Bad
Alignment of beams on outer side?	☑Good ☐ Avg. ☐ Bad
Shuttering leveling?	Good ☐ Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	✓ Correct ☐ Needs correction
Remarks:	

## Slab Steel check.

Notes:

- Mark  $\vee$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction. Mark  $\times$  for major mistake that requires correction by replacement or re-fixing. Mark  $\times$   $\times$  for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:
✓Good ☐ Avg. ☐ Bad		Steel check – slab extensions/joints	16.
Good Avg. Bad	•	Steel check - floating columns	15.
Good Avg. Bad	<	Electrical Conducting	14.
✓ Good ☐ Avg. ☐ Bad	1	Steel Check - Column steel overlapping length and cranking	13.
Good Avg. Bad	<b>V</b>	Covering blocks for slab	12.
Good Avg. Bad	<b>V</b>	Steel Check - Slab Extra Bars	11.
☐ Good ☑ Avg. ☐ Bad	<b>√</b>	Steel Check – Slab cranking & chairs	10.
☐ Good ☑ Avg. ☐ Bad	1	Steel Check - Slab spacing of bars	9.
Good Avg. Bad	<b>√</b>	Steel Check - Slab size of bars	&.
[√Good  Avg. Bad	J	Depth and width of beams	7.
☐Good ☐ Avg. ☐ Bad	<b>~</b>	Covering blocks for beams	6.
Good ☐ Avg. ☐ Bad	<u> </u>	Steel Check - Beams Bearing	5.
☐ Good 🗸 Avg. ☐ Bad	<	Steel Check - Beams Overlapping & Cranking	4.
✓ Good ☐ Avg. ☐ Bad	•	Steel Check - Beams Extra Bars	3.
☑ Good ☐ Avg. ☐ Bad	4	Steel Check - Beam size of bars	2.
✓Good ☐ Avg. ☐ Bad	<	Steel Check - Beam no of rods	1.
Qualitative Check (Good / Avg. / Bad)	Quantitative Check ( • or ×)	Item	S No
	The state of the s		