Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required		no.	Madhusudan	M. Tya Sindher Sign	Nilgri istate	43
eport to QC team. Proc fter submitting ATR or king corrections pointe pired.	MD Sign	30241	Sign	Sign	Project	Stage
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	5	Report filed and signed by PM?	an inter	10/1	Nilgmi wtat	
by QC. n. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No	Yes No	30/05/18	30/05/18	F1	30397

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rer	19	18	17	16	15	14	13	12	11	10	c	×	7	<u></u>	S	4	ယ	2	<u></u>	S No
Remarks	Other	Utility	Kitchen	Portico	Head-room	Terrace/balcony_2_	Terraee/-balcony l	Labby-2	Lebby 1- Drawna 1)	Dining	D)iawing	Toilet 4	Bedroom 4 (GB) 111 -	Toilet 3 ((T)) Coplan	Bedroom 3 (typ) (illy	Toilet 2 (KT) W	Bedroom 2 KB) (St	27	n 1 (MB)	Room
			<	1	١	١	ż	1	<	<	₹.		Κ,	<u> </u>	<	<	<	<	<	Skirting Provision (• or ×)
			1	1	١	١	1	[((<u> </u>		<u> </u>	.₹	<	K	<	<	<	Finishing around door frame (v or x)
			<	1	1	ļ	<	1	<	く	۲.	1	Κ.	<	<	<	<	<	<	Beams & columns finishing (v or x)
			<	ſ	Ţ	1	(1	İ	\	[1	(ţ	()	1	ſ	Finishing of lofts (v or x)
			<	{	1	1	{	•	<	<	<	9	<	<	入	ζ,	・メ	V	7	Electrical junctions finishing (v or x)
			1	1	1	1	1	(<	Ţ	Ţ	•	~		\	\ \	~	~	\	Window check (v or x)
			<	1	1	1	1		((Í		/	<	\	<u> </u>		>	I	Tiles provision (✓ or ×)
			7	١	1	1	ſ		1	1	†	ď.	/	<	1	<	1	<	1	Sink provision & size (✓ or ×)
			1	1	(!	1	1	(/		4	✓	<	<	<	<	<	<	Grooves for door frames (v or x)
			1	1	1	}	<	1	1	Į.	1		1	١	\	١		1	1	Balcony & terrace sill top finishing 10(• or ×)
			1	1	ļ	1				/	ĵ		1	((<	}	<	1	Screeding in bathroom & utility (• or ×)
			1	-	1	!	1	1	1		j	1	1	1	1	<	1	ζ	1	Screeding in 6" above FFL? (v or x)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good ☑ Avg. ☐ Bad
Plastering of compound wall & gate pillars (v or x)	~
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	☐Yes ☐No
Plastering quality of parapet walls (v or x)	<
Plastering and finishing of chajjas (vor X)	<
Remarks:	