Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager Machesudhan Sign	Prepared by Miley Svidler	Company Wilgivi estate	Villa No. 93	
QC report to QC team. Proork after submitting ATR corrections point required.	MD Sign	88787	Sign	L _s Sign	Project	Stage	
oceed only after recheck on QC report to QC team ed out in the QC report.		Report filed and signed by	Minesol	4.	May olat		
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.	
	Yes No	Lyres [No	08/03/18	08 03 18		29565	\

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed
- before starting painting, tiling & flooring.

<u>Plastering Check.</u> Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X Tor major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.

 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 12" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18	17	16	15	14	13-	12	11	10	9	8	7	6	2	4	з	2	,_	S No
Remarks	Other	Utility	Kitchen	Portie0	Head room	Terrace/ balcony 2	Terrace / balcony 1		Lobby 1—	Dining	Drawing	Teilet4	Bcdroom-4	Toilct3	Bedroom 3	Toilet 2 (じて)	Bedroom 2 (KB)	Toilet 1 (MT)	Bedroom 1 (Mも)	Room
			<	-	1		1	1	1	(<	ļ	Ţ	1	1	<u> </u>	<	<	<	Skirting Provision (• or ×)
			\	(1	1	1	١	1	١	<	ı	١	١	1	<u> </u>	~	<u>\</u>	<	Finishing around door frame (• or ×)
			~	1	J	1	})	}	<	<	1	1		}	۷,	~	\ \	<	Beams & columns finishing (v or x)
			<	{	•	1	1	1	1	1	1	١	١	-	1	١	-	~	<	Finishing of lofts (v or x)
			<	1		\	1	}	1	<	<	١))	١	۷,	<	<	<	Electrical junctions finishing (v or x)
		27	<	1	1	1		1	1	١	<	١	\	١	}	<	<	<	<	Window check (• or ×)
		35 31 32 33	<	1	1	9	})	1	١	1	1	1	١	1	<	1	<	1	Tiles provision (• or ×)
			<	1	١	1	1)	1	1	1	1)	}	<	1	<	j	Sink provision & size
			1	-	1	-	1)	J	1	<	١	١	})	<_	<	<	<	Grooves for door frames (✓ or ×)
			1	ſ	1])	1	}	1]	1	1	J)	1	1	1	1	Balcony & terrace sill top finishing 10(• or ×)
				1)	1)	J)	1	1	1]	1]	1	1	j		Screeding in bathroom & utility (v or x)
			1	1	1	1)))])	1	ì))	1	1	١	}	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	\
Overall quality of plastering?	☐ Good ¶Avg. ☐ Bad
Plastering of compound wall & gate pillars (v or X)	`\
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	N Yes □No
Plastering quality of parapet walls (vor X)	·\
Plastering and finishing of chajjas (v or x)	<
Remarks:	