Quality Control Check Repot.
Check Repot.
Stage: Before Casting Slab (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager A. SURESH	Prepared by G. RATESH	Company Voc (LLP)	Block No 136
report to QC team. Ifter submitting AT king corrections pour price.	MD Sign	34026		Sign	Project	Slab No.
Proceed only after recheck by R on QC report to QC team. sinted out in the QC report. A		3uo 26 Report filed and signed by PM?	C. C.	Colle	VOC	03
QC. TR not required.	For filling	PM?	Date	Date	Phase	Sl. No.
	Yes No	Yes No	30 107/19	30/07/19		34118

Slab Check.

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.

- Prepare Slab Dimensions Check Plan as follows:

 a. Show outer dimensions of slab. (Tolerance 2")

 b. Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts. (Tolerance 1")

- دن ح d. Show location of sunken slab.
 e. Print an A3 size plan.
 Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.
 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

4. Circle each correct dimension with green colour. Circle each incorrect dimension with led colour and inclinion	n colour. Circle each incol	Tect d	mension with rec	COTOUT SITE	וווכוונוטוו מכוממו מווווכוופוטוו וגכאל נס גני
Slab Dimensions Check Plan enclosed?	d?		Yes No	No	
Staircase - mid landing1	Specified ht:	•	Actual ht:	1,7	Within tolerance of ½"? Yes No
Staircase - mid landing 2	Specified ht:		Actual ht:	ì	Within tolerance of ½"? YesNo
Staircase width	Specified wd:	Í	Actual wd:	-	Within tolerance of ½"? — Yes No
Staircase slab thickness	Specified:	İ	Actual:	1	Within tolerance of 1/4"? Yes No

Quality Confrol Check Repot. Stage: Before Casting Slab (Villas)

Slab Steel check.

Notes:

- Mark for correct or minor mistake which does not require correction
 Mark for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. * Stage: Before Casting Slab (Villas)

, , , , , , , , , , , , , , , , , , , ,
X.
< .
ζ.
<
Quantitative Check (• or ×)