## Quality Control Check Repot. Stage: After Plastering (Villas)

	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	eport to QC team. Proceed the submitting ATR or cing corrections pointe ired.	commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after so Proceed with further work only after making Proceed with further work. ATR not required.	Recommendation:  Stop further work.  Stop further work  Proceed with furth  Proceed with furth
☐Yes ☐No	For filling	MD Sign		Checked By MD on
Yes No	Report filed and signed by PM?	33573	no.	Previous stage report no.
25/06/19	( Park Date	Sign	Bake Musali Ksishra Sign	Project Manager
25/06/19	There have Date	Sign	T vined Known	Prepared by
\$man-	Blecondale Phase	Project	大さろ	Company
33870	Sl. No.	Stage	41	Villa No.

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed
- before starting painting, tiling & flooring.

## Plastering Check.

Notes:

- Mark  $\checkmark$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction.

  Mark  $\times$  for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ¼".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Balcony & terrace sill

top finishing  $^{10}(\checkmark \text{ or } X)$ 

Screeding in bathroom & utility (✓ or 🗙)

Screeding in 6" above

FFL? ( ✓ or ×)

S No

Room

Lobby 1 Family 1

Bedroom 4

Toilet 3

Toilet 2 Bedroom 3

Toilet 1
Bedroom 2

1

Bedroom 1

Toilet 4
Drawing

Other

Head room Portico

Terrace/ balcony 1
Terrace/ balcony 2

Kitchen

## Quality Control Check Repot. Stage: After Plastering (Villas)

	Kemarks.
	Plastering and finishing of chajjas ( v or x)
	Plastering quality of parapet walls ( or x)
☐Yes ☐No	Is plastering of compound wall and villa external walls 6" below FFL of setbacks?
<b>*</b>	Plastering of compound wall & gate pillars ( v or x)
Good Avg. Bad	Overall quality of plastering?
	Miscallaneous check