Quality Control Check Repot
Stage: Before Casting Slab (Villas)
illas)

Block No Company Prepared by	7. Ser James	Slab No. Project Sign	Ark Gulmolor	SI. No. Phase Date	33073
. repared of) - Jas Kurner	d	3.8100		1111
Project Manager	Zatar Hossais	Sign	D.	Date	2/9/19
Previous stage report no.	no. 21885		Report filed and signed by PM?	Ų;	LYes ∐No
Checked By MD on		MĎ Sign		For filling	∐Yes ∐No
Recommendation: Stop further work Stop further work Proceed with furt Proceed with furt	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. AT Proceed with further work. ATR not required.	o QC team. Promitting ATR rections points	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	not required.	e <u>e</u>

Slab Check. Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for easting. Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconics (Tolerance 1") Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

3. Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted	r height. Measure fr	om SFL to S	FL. Check stair	case of lower	Hoor that has been casted.	*
4. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention	n colour. Circle eac	h incorrect d	imension with r	ed colour and	mention actual dimension next to it.	1.
Slab Dimensions Check Plan enclosed?	d?		UYcs ∐No	No		`
Staircase - mid landing1	Specified ht:	£,7 = °,7	Actual ht:	インパッ	Specified ht: んっい Actual ht: リンパ Within tolerance of ½"? 以Yes \ No	以Yes □No
Staircase - mid landing 2	Specified ht:	l d	Actual ht:	(Within tolerance of 1/2"?	□Yes □No
Staircase width	Specified wd:	6.6"	Actual wd:	6.511	Specified wd: 6!6" Actual wd: 6!5" Within tolerance of 1/2"?	Yes YNo
Staircase slab thickness	Specified: $S^{\prime\prime}$ Actual:	1.5	Actual:	511	S'' Within tolerance of 1/4"? Yes \(\text{No}\)	Yes No
		2000				

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

	Remarks:	Column steel overlapping	Shuttering leveling? .	Alignment of beams on outer side?	Quality of Bracing Provided?	18" extension to beam bott	Quality of centering, rod bending and concreting?	Quality of centering, for bending and concreting.
		Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)		ter side?	:d?	18"extension to beam bottom runners on outer side provided?	ending and concreting?	ending and concreding.
					÷			
		☐Correct ☐ Needs correction	Good V Avg. Bad	☐ Good ☐ Avg. ☐ Bad	Good ∴Avg. ☐ Bad	Yes WNo	. Good ✓ Avg. Bad	

Slab Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X x for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

				Remarks:
	Good Avg. Bad		Steel check – slab extensions/joints	16.
	☐ Good ☐ Avg. ☐ Bad	•	Steel check – floating columns	15.
	☑ Good ☐ Avg. ☐ Bad	<	Electrical Conducting	14.
	Good Avg. Bad	<	Steel Check - Column steel overlapping length and cranking	13.
	☐ Good ��Avg. ☐ Bad	<	Covering blocks for slab	12.
	☐ Good []/Avg. [] Bad		Steel Check - Slab Extra Bars	F
	☐ Good []Avg. ☐ Bad	<	Steel Check Slab cranking & chairs	10.
	☐ Good [V Avg. ☐ Bad		Steel Check - Slab spacing of bars	9.
W 8	⊡ Good MAvg. ☐ Bad	< <	Steel Check - Slab size of bars	8
	☐ Good ∏Avg. ☐ Bad	<	Depth and width of beams	7.
	☑Good ☐ Avg. ☐ Bad	<.	Covering blocks for beams	6.
	☐ Good ☑ Avg. ☐ Bad		Steel Check - Beams Bearing	5.
	☐ Good ☐ Avg. ☐ Bad	< · ·	Steel Check - Beams Overlapping & Cranking	4.
	☐Good ☐ Avg. ☐ Bad		Steel Check - Bcams Extra Bars	3.
	☑ Good ☐ Avg. ☐ Bad	<:	Steel Check - Beam size of bars	2.
	YGood Avg. Bad	~	Steel Check - Beam no of rods	1.
	Qualitative Check (Good / Avg. / Bad)	Quantitative Check . (v or x)	Item	S No