Quality Con-
Quality Control Check Repot.
ot. Stage:
Stage: Before Casting Slab (V
asting Slab (Villas)

Recommendation:  Stop further work. S  Stop further work.  Proceed with furthe  Proceed with furthe	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck to Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		0.	A. SURCSII	G-RAJESH	10 c (11 P)	127
QC team. Pr mitting ATR rrections poir	MD Sign	83611	Sign	Sign	Project	Slab No.
ecommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.		Report filed and signed by PM?	Ç	STAN WAR	VOC	02
C. not required.	For filling	<i>A</i> ?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	√Yes □ No	20/06/19	2006 119	1	33639

## Slab Check.

## Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
   Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
  Show length and width of balconies (Tolerance 1")
  Show inner dimensions of ducts. (Tolerance 1")
  Show location of sunken slab.

- e. Print an A3 size plan.

  Mid landing height is no, of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

  Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension.

4. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.	n colour. Circle cac	h incorrect	dimension with re	ed colour and	d mention actual dimension next to	o it.
Slab Dimensions Check Plan enclosed?	d?		Yes No	No		
Staircase - mid landing1	Specified ht: 313 "	312"	Actual ht	31811	Within tolerance of 1/2"? Yes No	✓Yes ☑No
Staircase - mid landing 2	Specified ht:	4	Actual ht:		Within tolerance of ½"? YesNo	Yes No
Staircase width	Specified wd:	6)611	$\mathcal{L}^{1}\mathcal{E}^{11}$ Actual wd:	19,9	Within tolerance of ½"? ☐Yes ☐No	☐Yes ☐ No
Staircase slab thickness	Specified:	5	5 h Actual:	5=	Within tolerance of 1/4"? Yes No	✓ Yes □ No

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)		on other side?		Onality of Bracing Provided?		Onelity of contains and religing and concreting.
				Correct Needs correction	☐ Good ☑ Avg. ☐ Bad	☐ Good [☑ Avg. ☐ Bad	Good Avg. Bad	Yes No	Good Avg. Bad	

## Slab Steel check. Notes:

- Mark for correct or minor mistake which does not require correction

  Mark for minor mistake that requires minor correction.

  Mark for major mistake that requires correction by replacement or re-fixing.

  Mark for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			INCILIDITAD.
Good Avg. Bad	And State Company	STATE STATE STATE CARCINSTOLLS, JOHNS	Remarks
U Good Avg. Bad	Company,	_	16.
<b>A</b>	4	Steel check – floating columns	15.
Good Avg. Bad		L. Electrical Conducting	14.
☐ Good ☑ Avg. ☐ Bad		<u> </u>	
☐ Good [ Avg. ☐ Bad	-		13
Good Avg. Bad		-	13
☐ Good ☑ Avg. ☐ Bad		Steel Check - Slab Extra Dom	
☐ Good ✓ Avg. ☐ Bad			10.
Cooca Cive. Dati	<	Steel Check - Slab spacing of hars	9.
		Steel Check - Slab size of bars	
Good Avg. Bad			
☐ Good ☑ Avg. ☐ Bad			1 0
☐ Good ☑ Avg. ☐ Bad			y ;
☐ Good ☑ Avg. ☐ Bad	5		<i>y</i> :
☐ Good ☑ Avg. ☐ Bad		Steel Check - Beams Extra Bars	4
Good Avg. Bad			n i
			2
(Good / Avg. / Bad)	( • or ×)	1. Steel Check - Ream no of rode	-
Onalitative Cheek	Ouantitative Check	No	SNO