Quality Control Check Repot. Stage: After Plastering (Villas)

Company Nikon Estates	Stage Project	Nolgini Estates	Sl. No. Phase Date	3428 H
Prepared by	Sign	1. Land	Date	16 68119
Project Manager	Sign	M. West	Date	16/08/19
Previous stage report no.	33738	Report filed and signed by PM?	ed by PM?	Yes No
Checked By MD on	MD Sign		For filling	Yes INO
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	report to QC team. Pro after submitting ATR o aking corrections point quired.	ceed only after recheck n QC report to QC team ed out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark \checkmark for correct or minor mistake which does not require correction
- Mark \times for minor mistake that requires minor correction. Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Screeding in 6" above FFL? (• or ×)

		 	_	_							_											
		Ren	19	18	17	16	15	14	13	12	11	10	6	8	7	6	5	4	သ	2	1	S No
	ω	Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony 2	Terrace / balcony 1	Lobby 2	Lobby 1	Dining	Drawing	Toilet 4-	Bedroom 4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom l	Room
e e							1	alcony 2	alcony 1								}		KIS	MI	M 15	
		á			<	Libra	1	Ì	Bay comme	2	Front Lane	<	* ✓	i	ì	1			\checkmark^{i}		<	Skirting Provision (• or *)
					5	į	<u> </u>	C some	- Park	ĺ		Pos	✓) (January	2	\sim	<,	V	<,	Finishing around door frame (• or ×)
					۷,	ζ,	\	Vienne	junto	1	- Comment	<	<,	· ·	1	î	ì	~	4	۷,	4	Beams & columns finishing (v or x)
					۷,	3	Et.alum	G/Season.	6	ĥ	1	Ì	1	N. Control	ì	- menuting	١	e' y	<,	1	4.	Finishing of lofts (v or x)
Page 2 of 3					4	<	۷,	C. Carrier	Į	1		۷,	<	C ye	9	ì	7.	<.	Š	4,	Ś	Electrical junctions finishing (v or x)
ပြ					۷	1	<_)	1	i	<	۷,			9	ì	۷.	Κ.	į,	8	Window check (✓ or 🗙)
					۷,			1	1		1		6 1	7	3			<		5		Tiles provision (✓ or 🗙)
5					<		1	7117	1	ſ	270-	157	ì	** Carrier	Elita	Î		4	ŗ	1	Ą	Sink provision & size
					5	,	2	1	2004	1	, and a	i.	۷	F	-46.13	C.Line	7		14	<	<,	Grooves for door frames (v or x)
	-					71	51	: S	1	f	Ĵ	0.00	î	2	1	()) at	6.7	er i	,	1	E 17	Balcony & terrace sill top finishing 10 (v or x)
					1		1			1	1	, A	Ì	į		7	ì	2	1	6.12	* 1	Screeding in bathroom & utility (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

	Remarks:	Plastering and finishing of chajjas (v or x)	Plastering quality of parapet walls (• or ×)	Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Plastering of compound wall & gate pillars (or x)	Miscellaneous check Overall quality of plastering?
		<	<	× 100	Ves No	☐ Good ☑ Avg. ☐ Bad