Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		no.	T-NOCHU.	S. Suni Kung	Vista Homes	F-803
port to QC team. Proceed real submitting ATR on ing corrections pointed ired.	MD Sign	3033	Sign	Sign	Project	Other
eed only after recheck QC report to QC team I out in the QC report.		Report filed and signed by PM?	1 and my	A/C	Visto Hopes	
ck by QC. am. rt. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No	Yes No	1916119	19/6/19	J***	33640

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark **X** for minor mistake that requires minor correction.

 Mark **X** for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- 9.8
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Z	_		1		1		9	∞	7	6	S	4	j	K 5		
NGHAINS	ems	15	14	13	-	11	10										S No
ALAS	arks	Other	Other	Kitchen	Utility/balcony-3.	Utility / balcony-2	Utility-/ balcony 1	Lobby-1-	Dining	Drawing	Toilet-3	Bedroom 36 Bed	Toilet 2 CATON	Bedroom 2 K. Bea	Toilet 1 March	Bedroom 1 M. (30d)	Room
				<	F 85 . 10 .	Ż	(1	<	d'annual de la company de la c	ζ.	<	ς	ς	ζ.	Skirting Provision (✓ or 🗙)
				<	184	ζ	7	4, 20-m	427	<	Obove and	1	(ζ.	×	(Finishing around door frame (✓ or 🗙)
				<	age and the	(<	- menter of the second	Commercial	<	A. Carrier and	<	<	5	<	(Beams & columns finishing (• or ×)
				(-	9.7		\$ Carpena		Control of the Control	As an	Tiple makeum	Branc	4700	Finishing of lofts (• or ×)
				<		(ζ,	1	7	5			<	<	1	<	Electrical junctions finishing (✓ or ×)
				ζ,	A STATE OF THE STA	Comments of the same	A powerful	T) Server	· in the second	-		<		(M	(Window check ⁶ (✓ or X)
				ζ	g .	<	G	All many and core .	-	1		4	5		<	Ghirana	Tiles provision (✓ or X)
				X.			}		1	Ca. 1497-147	Q	effect, r	J	9	61.70	and the same of th	Sink provision & size (✓ or X)
				-	1	ζ	g.	Ti dan managara		}	9	<	ζ	ζ	ζ	5	Grooves for door frames (✓ or ×)
				CATANGO PAR			37	C.The -www.	A	491-10-10-10-10-10-10-10-10-10-10-10-10-10	Mile Same	· Section .		G: 17 July	Bertand	E land of the	Balcony & terrace sill top finishing(✓ or X)
				9	ga na na	5	1	41 1.00-	ets	gr.	Out	distance comme	6.0 manus	All for some of	871	CONT. Mary	Screeding in bathroom & utility (• or ×)
)	Par. 14	ζ.))))	,	7	7)	ř.	P. Demoka	Screeding in 6" above FFL? (or ×)