	A COUNTY OF THE PARTY OF THE PA		
	ľ	<	
		=	,
	3		
			֓֡֡֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜
COLUMN TOWN	~~		
	1		
0000	7	/	2
	,	3	
			,
	101	3	•
	(٥)
	TITLE	7	
Ì	\ - -		
	III	•	
I	1		1
Į	CHILA I HUMAN HITHER I WHITEN COLORS AND A STATE OF		
	V III		-
l	À	9	

Recommendation: Stop further work. Submit ATR on QC reporting Stop further work. Proceed with work after superiority Proceed with further work only after making Proceed with further work. ATR not required	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	MD Sign) 29536	A- Swesh Sign	P. Soi Kumon Sign	Voc (LLP) Project	<u>-</u>
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		Report filed and signed by PM?	()	Proch	TO C	
by QC. 1. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	L√Yes □ No	- 4 8 - 1 8	11 W 11 %	}	24362

Plinth Beam Check,

Notes:

5.4

- Inspection should be done before casting of plinth beam Yellow enunct paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

 c. Print an A3 size plan.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?
☐ Yes ☐ No

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	}
Quality of centering, rod bending and concreting?	☑ Good ☐ Avg. ☐ Bad
Have rods for staircase slab been provided?	√Yes □ No
Quality of Bracing Provided?	☐ Good [☑ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good [☑ Avg. ☐ Bad
Brackets for elevation features provided?	Yes No NA
Level marking at 2' above FFL is made?	☐ Yes ☐ No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	□ Correct
Pedestal/column0 – self check report attached?	Yes No
Remarks:	

Plinth Beam Steel check.

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X x for major mistake that requires correction by replacement or re-fixing.
 Mark X X x for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Rennrks:	7.	0.	, j.	4.	i.	, i	· -	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	<	<	<,	<	<	ζ,	<,	Quantitative Check (• or ×)
	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	☐Good ☐Avg. ☐Bad	Good Avg. Bad	Good Avg. ☐ Bad	Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)