| Quality Control  |  |
|--|--|
| Check Repot.   |  |
| Quality Control Check Repot. Stage: Before Casting Slab (Villas) |  |
| e Casting Slab (Villas)  |  |
| illas)   |  |

| Recommendation: Stop further work. Stop further work. Proceed with furthe   | Checked By MD on | Previous stage report no.      | Project Manager |                 | Company         | Block No |
|---|------------------|--------------------------------|-----------------|-----------------|-----------------|----------|
| Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck be Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.         |                  | o. 34826                       | NK P            | Sissual Actions | HOH             | 89       |
| QC team. Pr<br>nitting ATR<br>rections poin   | MD Sign          |                                | Sign            | Sign            | Project         | Slab No. |
| Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required. |                  | Report filed and signed by PM? | al              |                 | AVA GILLIMO-Nag | 93       |
| C. not required.  | For filling      | M?                             | Date            | Date            | Phase           | SI. No.  |
|   | ☐ Yes ☐ No       | Yes No                         | 13/18/19        | 3/180/10        | 1               | 34904    |

## Slab Check.

Notes:

- Inspection should be done before easting of slab at each stage i.e. when the slab is ready for easting.
- Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1") Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

|                                      | and in        | 100001 | TITOTOTO WILLIAM CO. | יסוסתו מד | in mention actual annementation feet to 15 |            |
|--------------------------------------|---------------|--------|----------------------|-----------|--|------------|
| Slab Dimensions Check Plan enclosed? | d?            |        | Yes No               | 0         |  |            |
| Staircase - mid landing1             | Specified ht: |        | Actual ht:           |           | Within tolerance of ½"? Yes No             | ☐ Yes ☐ No |
| Staircase - mid landing 2            | Specified ht: |        | Actual ht:           | 9         | Within tolerance of 1/2"?                  | ☐Yes ☐No   |
| Staircase width                      | Specified wd: |        | Actual wd:           | 1         | Within tolerance of 1/2"?                  | ☐ Yes ☐ No |
| Staircase slab thickness             | Specified:    |        | Actual:              |           | Within tolerance of 1/4"?                  | ☐Yes ☐No   |
|                                      |               |        |                      |           |  |            |

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

|  |  |  | INCIDENTAL. | rrms and committies (overlapping length should be 45 to 50 D) |               | Shuttering leveling? | טוו עמוכן פונוכי | 200           | Quality of Bracing Provided? | runners on outer side provided? |               | Quality of centering, rod bending and concreting.  Quality of centering, rod bending and concreting. |
|--|--|--|-------------|---|---------------|----------------------|------------------|---------------|------------------------------|---------------------------------|---------------|--|
|  |  |  |             | Correct Needs correction                                      | Uood Avg. Bad | )                    | Good Avg. Bad    | Good Myg. Bad |                              | Yes No                          | Good Avg. Bad |  |

## Notes: Slab Steel check.

- Mark refor correct or minor mistake which does not require correction
   Mark requires minor correction.
   Mark requires minor correction.
   Mark requires correction by replacement or re-fixing.
   Mark requires corrected.
   Columns overlapping length should be 45 to 50 D.

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

|                                      |   | 5:  | Remarks: |
|--------------------------------------|---|---|----------|
| Good Avg. Bad                        | Company of the                                  | Steel check – slab extensions/joints          | 10.      |
| Good Avg. Bad                        | )   |   | 15.      |
| Good Avg. Bad                        | (   | -   | 14.      |
| Good Avg. Bad                        | (   |   |          |
| Good Avg. Bad                        |   |   | 13       |
| Good Avg. Bad                        | <   |   | 12       |
| Good Avg. Bad                        | 5   |   |          |
| Good Avg. Bad                        | (   |   | 10       |
| Good Avg. Bad                        |   |   | 9.       |
| ☐ Good ☐ Avg. ☐ Bad                  | ,   | -   | .8       |
| ☐ Good ☐ Avg. ☐ Bad                  | 7   |   | 7.       |
| ☐ Good ☐ Avg. ☐ Bad                  |   |   | 6.       |
| Dad                                  |   |   | 5.       |
| Good Avec Dod                        |   | 4. Steel Check - Beams Overlapping & Cranking | .4       |
| Good Avg. Bad                        |   | 5. Steel Check - Beams Extra Bars             | 3.       |
| Good Avg. Bad                        | 5   | -   | ) I      |
| 1 11 -                               |   |   | 2        |
| Qualitative Check (Good / Avg / Rad) | Quantitative Check ( \sigma \text{or } \times ) |   |          |
|                                      |   |   | N NO     |