## Quality Control Check Report. Stage: After column Casting (villas)

Block No. 91 Column No. 01 SI. No. 29713  Company Voc Ul Project Voc Phase  Prepared by M. Tija Snidu Sign AA Date 17/03/18  Project Manager A C
M. Tiga Sindu Sign AA Date  A Constant Sign
M. Tija Sriche Sign HA Date  A Country Sign
A Company Sign Nate
Previous stage report no. 2936 Report filed and signed by PM?
Checked By MD on MD Sign For filling Yes \( \square\) No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.

### Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1") Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

0	J
Theck Plan enclosed?	Circle each correct difficult with green colour. Circle each incorrect dimension with red colour and m
☑Yes □No	ision with red colour and mention actual dimension next to it.

### Slab Dimensions Check.

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
  Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Circle each correct dimension with oreen colour. Circle each incorrect dimension with red color

Specified thickness of slab?	Slab Dimensions Check Plan enclosed?	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and i
Actual thickness of slab?	☐ Yes ☐ No —	e each incorrect dimension with red colour and mention actua
		al dimension next to it.

# Quality Control Check Report. Stage: After column Casting (villas)

		Remarks:
- Dau	L Good MARS. L Dad	Quality of infrastructure for curing.
T Box	Z I CS	Is the pressure in the curing pipe more than 15' head?
	2 June	Frequency of curing in number of times a day (enquire from labourers)
	0000	Distance of tap from furthest distance that requires curing. (max permitted 100')
	K 19	Gunny bags used for column curing?
	╗	Drum (200 lts) provided for curing?
}	1 -	Bund size is less than 100 sft?
		Bunds for curing made on slab?
		Remarks:
		Demonifica
Yes No		Have 6 cubes each for columns and slab casted and numbered for testing?
Ц	than 1"	Number of beams that are sagging, bulging, caved or deflected in the slab by more than
Coop N VAR. C Par		Are the honey combs is slab and columns packed?
Carl Ava Rad		Number and size of honey combs?
Ligh Medium Llow		Quality of starters?
Good Avg. Bad		Quality of centering, rod beilding and concerns.
☐ Good ☐ Avg. ☐ Bad		Quality of centering, rod bending and concreting.

# Quality Control Check Report. Stage: After column Casting (villas)

### Columns height, plumb, steel & level marking check.

Notes:

- Mark V for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark XX for major mistake that requires correction by replacement or re-fixing.
   Mark XXX for major mistake that cannot be corrected.
   Tolerance: Plumb 0.25".

S No	Col No.	Col type	Heigh	o Col No. Col type   Height in ft   Steel ( • or ×)	Steel (	Steel ( v or x)	Honeycombs	Plumb ( or x)	or X)	marked on
	2000	,	Spec.	Actual	No of	Size of		Side 1	Side 2	column?
	_				rods	rods		\		RYV22 □NIA
-	Þ	C	1.t.s	1,9/4:18	<	<	<	<	<	
2.	2	CZ	12.18	114.18	<	<	<	<	<	$\neg \mid \Gamma$
<u>.</u>	7	C,	14.18	14.00	<	<	<	<	<	╗╟
4.	go ?	3	114-18	812161	<	<	<	<	<	╗┌
5.	33,	5	14.8	8-21/21	<	<	<	K	<	No. I No.
6.	20	C	14.8	14.8	<	<	<	<	<	
7.	5	Ch	15	S-1	<	<	<	. <	<	╗
8.	62	5	14:8	8.8	<	<	1	<	<	7
9.	5		-/ S:	7 3	<	<	<	<	1	╗
10.	9		81.4n	8,5,1	<	く	<	<	<	No.
11.	03	C2	81411	8.5	<	<	<	<	. <	1
12.	hd.	5	17.3	8:81	<	<	<	<	. <	$\neg \mid \Gamma$
13.	77,	53	814	81.511	<	<	\ \ \	, <	<	
14.	63	7	8.4.	8.50	<	E	<	<	<	
15.	Z.	2	1. Es	8.81	Z	1				
16.										
17.	_									
18.										7
19.										_  [
20.		8		2						