

# Quality Control Check Repot. Stage: After Column Casting (villas)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	Checked By MD on MD Sign For filling Yes UN		Sign Date	sign V	Company Sov Project Sov (LLP) Phase TX	Block No. 87 Column No. 02 Sl. No. 33254	
	Yes No	Yes No	25/3/19	25/3/19	X	33254	

#### Columns Position Check.

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

### Columns Position Check Plan enclosed? M Yes N N

#### Slab Dimensions Check.

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
  Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.

e. Print an A3 size plan.			
2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention a	rect dimer	asion with red colour and mention actual d	limension next to it.
Slab Dimensions Check Plan enclosed?		Yes No	
Specified thickness of slab?	5	5" Actual thickness of slab?	57
			The state of the s

# Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good [☑ Avg. ☐ Bad
Quality of starters?	■ Good Avg. ☐ Bad
Number and size of honey combs?	_] High [ ] Medium. ☑ Low
Are the honey combs is slab and columns packed?	Good ✓ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	
Have 6 cubes each for columns and slab casted and numbered for testing?	∏Yes □ No
Remarks:	
Curing.	
Bunds for curing made on slab?	
Bund size is less than 100 sft?	
Drum (200 lts) provided for curing?	
Gunny bags used for column curing? ☐Yes ☐No	
Distance of tap from furthest distance that requires curing. (max permitted 100')	
Frequency of curing in number of times a day (enquire from labourers)	And the special control of the special contro
Is the pressure in the curing pipe more than 15' head?	
Quality of infrastructure for curing.	Bad
Remarks:	

### Notes: Columns height, plumb, steel & level marking check.

- Mark v for correct or minor mistake which does not require correction
   Mark x for minor mistake that requires minor correction.
   Mark x for major mistake that requires correction by replacement or re-fixing.
   Mark x x for major mistake that cannot be corrected.
   Tolerance: Plumb 0.25".

Circle actual height of columns if level differs from specified height by more than 1".

No | Col No. | Col type | Height in ft | Steel ( vor x)

	20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	Ŏ.	1 9	6	5.	4.	3.	2.		-		S No
		_															4	7	£3			<u> </u>	Col No.
											1101						CU	Cz	5	0		<u> </u>	Col type
	_												_			,	ינין ב	ったこと	8-7"	8-7"		Spec.	Heigh
																9	2/12	יבים	a 1 1	18:3		Actual	Height in ft  Steel ( v or x)
																1	\			۷,	rods	No of	Steel (
																<	\	<		۷.	rods	Size of	Steel ( or x)
																<	<	\ \ \		<i>y</i>		-	Honeycombs
-																<	<		<	/		Side 1	Plumb
																K	<	<				Side 2	Plumb (v or x)
∠ Yes ∠ No	7   [	1	7	7	7				Yes No	╗	$\neg \mid \vdash$		7	☐ Yes ☐ No	∐Yes ∐No		1	3 5	Vec	VYes No	column?	marked on	Reference level