Flat No. Company Prepared by Previous stage report no. Project Manager Checked By MD on Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work. ATR not required. proceed with further work only after making corrections pointed out in the QC report. ATR not required. Subba Reddy J.907 SNC Quality Control Check Repot. Teasvidu Other Project Sign MD Sign 1488 Stage: After Plastering (Apartments) Report filed and signed by PM? 工 た S1. No. Phase Date Date For filling 09/12/17 YYes LINO Yes

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Mark \checkmark for correct or minor mistake which does not require correction

Mark X for minor mistake that requires minor correction.

Mark XX for major mistake that requires correction by replacement or re-fixing.

Mark $\times \times \times$ for major mistake that cannot be corrected.

9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".

Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")

Sill top must be of uniform thickness, correct height, at one level & without broken edges. All doors frames should have 1/2" grooves.