Quality
Control
y Control Check Repot.
Stage: After Brickwork (Apartment
Brickwork (
(Apartments)

11 . 11	})	The second secon	1	
FIRE NO.	6-005	Others	١	SI. No.	28598
Company	BNC	Project	Hy	Phase	k)
Prepared by	M Tya Sidher	Sign	4	Date	41/21/30
Project Manager	Subba Reddy	Sign	182	-Date	08/12/14
Previous stage report no	0.	90588	Report filed and signed by	d by PM?	No □No
Apartment No		Other		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after su Proceed with further work only after making of the proceed with further work. ATR not required.	Submit ATR on QC re Proceed with work af ir work only after mak ir work. ATR not requ	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	eed only after recheck be QC report to QC team. I out in the QC report.	y QC. ATR not required.	

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check.

Notes:

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- 3. Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- 5. Wall thickness should be as per plan. Usc of 4", 6" & 8" blocks must be checked.
- 6. All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- 9. Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: 1")
- 3. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than I'in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	15	14	13	12	11	10	9	∞	7	6	, U	4	·	n t	<u>ي</u>	S No
Remarks	Other	Other	Kitchen	Utility/balcony 3-	Utility / balcony 2_	Lility / balcony 1	-Lobby-1	Dining	Drawing	To Het-d-	Bedroom 3 ((4b)	<u>'</u>	7 n	3	,	Redroom 1 (MB)
			<	1	4	<	ļ	\	<	1	<	<	<	, <	\	Wall thickness (• or ×)
			<	1	<	ζ,	!	<	<	_	\ \ !	<	<	\	,	Beds in walls ' (• or ×)
			<	1	<u>ح</u>	<	Ţ	<	<	1	<	<	<	<	. <	Chicken mesh
			<		4	<	1	<	<	1	<	<	<	<	<	External brickwork & beam joint (or x)
			<	İ	4	\	1	<	<	1	<	<	<	<	<	
			1	1	1	1	!	1	5	1	(I	1		1	Room Dimensions Difference in inches
				1	۷.	`	!	<	5	1	<		<	<	<	Diagonal (v or x)
			-	1		1	1 1	\		1	{	1	ſ		i	Diagonal Difference in inches
			!	1	11.				1	1	\	1	i,	J	1	Diagonal Difference in inches Balcony sill level (or x)
		<		<		()		< <		1	1		<	<	<	Room Height
		0	A	_ =	1	7,		י אמן	A	1	1.1	1/	-	-	Ava	Plumb of walls (Good/Avg./Bad)
		<		. <	<			<				\		۷,	<	Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐ Good ☐ Avg. ☐ Bad
Specify rooms that need correction:	
The second secon	Superior Control of the Control of t
Misc. Checks.	
Was 3.75 CFT proportion box provided?	☐Yes ☐ No
Condition of proportion box?	☐ Good ☑ Ávg. ☐ Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☐ Cant' say
Is the Apartment cleaned for plastering?	☐Yes ☐No
Wastage?	☐ High Medium ☐ Low
Storage of building material like bricks sand and cement.	☐ Good NAvg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	☐Yes ☐No
Remarks:	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing. Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Re	15	14	13	12	=	10	9	∞	7	6	S	4	w	2	-	S No
Remarks:	Other		Kitchen	١.	-	Utility / balcony 1	Lebby 1 · · ·	Dining	Drawing	Toilet-3	Bedroom 3 (GB)	Toilet 2 (CT)	Bedroom 2 (KB)	Toilet 1 (MT)	Bedroom 1 (れら)	Room
			Ţ	-	4		-	1	<	1	~	<	<	<	<	Door size, face and position (✓ or ×)
		***********	-	1	<	ì	ļ	{	1	ſ	く	1	<	}	<	Brick at bottom of door frame (✓ or 🗙)
			(ľ	<	1	I	ſ	<u> </u>	-	く	<	<	<	<	Door lentil level (v or x)
			(~	1	-	1	<	-	~	<	<	<	<	Door diagonal check
			-		く	1	1	1	4	[~	く	<	<		Door Plumb - two sides
			1		~	}	Į	1	4	1	7	<	~	<		Door frame black Japan/ wood primer/Peelambar check (vor X)
			<	Ţ	1	}			1	(く	く	<	<		Windows lentil & sill level (✓ or 🗙)
			\	1	1	}	ļ	1	1		~	<	<	<	7	Windows size (✓ or 🗙)
			<		1	1		1	1	{	~	۲	<	<	<	Windows - template depth & diagonal (✓ or 🗙)
			人		1	1	ļ	ļ	١	1	く	<	<	〈		Windows - template powder coated (• or X)
			70	١		j	1	1	1	1	ſ	J	\	١	j	Loft & Kitchen platform required ? (Yes or No)
			1	1	1	1	ļ	1	1	ļ	١	l	1	١		Loft & Kitchen platform provided (v or X or NA)
		2		1	1	1	1]	-	1	1		1		Loft & Kitchen platform slope (v or X)

Quality Control Check Repot. Stage: After Brickwork (Apartments)