uality Control Check Repot. Stage: After Brickwork (Apartments)	uality
Repot.	Control
ļ	Check Repor
After Brickwork (Apartments)	
vork (Apartments)	After Bricky
rtments)	vork (Apa
	rtments)

Recommendation: Stop further work. Stop further work Proceed with furth	Checked By MD on	Apartment No	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.	8
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		8	no.	7-MOOTIL	5-Sunitatumos	Vis.ta, Hames	G-408	
eport to QC team. Proceeds a submitting ATR on cing corrections pointed ired.	MD Sign	Other	97587	Sign	Sign	Project		Others
eed only after recheck l QC report to QC team. I out in the QC report.			Report filed and signed	+100/	1	vista Homes		
by QC. ATR not required.	For filling	Other	d by PM?	Date	Date	Phase		Sl. No.
	☐ Yes ☐ No		Yes No	1161140	07/100/17 1 (00/17)	7	98583	

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check,

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark **X** for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")12. Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than I"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	1	カ	14	13	12	=	0.1	9	∞	7	6	5	4	w	2	1	S No
Remarks	Cuici	Other	Other	Kitchen	4-Jtility / balcony 3-	Utility / balcony 2 -	Utility / balcony 1	Lobby 1	Dining	Drawing	Foilet3-	Bedroom 3 Krbed	Toilet 2 CATO!	Bedroom 2 K. Bed		Bedroom 1 M&Cd	Room
				~	,	ζ	5	1	1	ς		ς	٢	ς.	۲	ς.	Wall thickness (✓ or ×)
		1000		~	•	ζ	5	!	ſ	۲		<	ς.	(<	(Beds in walls (✓ or X)
		2003		<u> </u>	•	ζ	5	1	1	ς.	١	ς	5	ζ	<	ς	Chicken mesh (✓ or 🗙)
				1	,	5	ς.	1	1	<	1	١	1	1	,	-	External brickwork & beam joint (or x)
				ς	1	۲	5	1	1	<	1	5	ς	ζ	5	ς,	Room Dimensions (• or ×)
)	1	1	1	7		3	1)	1)))	Room Dimensions Difference in inches
				ς.	1	ζ.	ς	1		ς)	ς,	5	ς.	<	5	Diagonal (• or ×)
				١	1	1	1	1	1	1	•)	١	ı	1	}	Diagonal Difference in inches
				1	1	ì	1	1	1	ı	1	1	١	١	١	١	Balcony sill level
				ζ		۲	ς	1	1	ς	1	(1	7	1	ζ	Room Height
				~	1	~	/~)	Y	ור	ļ	11	11	11	11	AVO	Plumb of walls (Good/Avg./Bad)
				7))))		1	1	1	1	1	1	1	Alignment of beams and walls - Nos.

Quality Control Check Repot. Stage: After Brickwork (4)	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐ Good ☐ Avg. ☐ Bad
Specify rooms that need correction:	``

Misc. Checks.	
Was 3.75 CFT proportion box provided?	☐Yes ☐No
Condition of proportion box?	☐ Good ☑ Avg. ☐ Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☐ Cant' say
Is the Apartment cleaned for plastering?	☐Yes ☐No
Wastage?	☐ High ☐ Medium ☐ Low
Storage of building material like bricks sand and cement.	☐ Good ☐ Avg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	☐Yes ☐ No
Remarks:	

Door Frames & Windows check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")

 Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Ren	15	14	13	12		01	9	∞	7	6	S	4	သ	2		S No
Remarks:	Other	Other	Kitchen	Utility/balcony-3-	Utility / balcony 2	+0tility / balcony 1	Łobby T	Dining	Drawing	Toilet-3—	Bedroom 3 & Octo		Bedroom 2 K. Ded	Toilet 1 M.Toi	Bedroom 1 M. Oed	Room
			1	1	ς	1	1	•	ς.	1	ς.	ς	ς	٢		Door size, face and position (or X)
			İ	1	۲	١	}	}	٢	١	۲	<	(ς		Brick at bottom of door frame (v or X)
	33	ě	1	-	5	1	i	1	<	١	(ς	<	((Door lentil level (v or X)
			1		ς	1	1	ı	<	1	<	۲	5	ς	(Door diagonal check (v or X)
			1	1	ς	1	1	1	ς.	ì	ς.	<	(ς.	(Door Plumb - two sides (✓ or 🗙)
	60000		1	Ì	ς	١	١	1	ς,	ļ	(X	5	<	١	Door frame black Japan/ wood primer/Peelambar check (v or X)
			1	1	1	1	1	1	1	١	(ς	(ς	<	Windows lentil & sill level
			5	1	1	1	1	1	1	1	(ς	ζ	((Windows size (✓ or 🗙)
			ς	١	١	1	1	1	Į	1	(ζ	ς	<	(Windows - template depth & diagonal (✓ or 🗙)
			ζ	•)	1	atta-	1	1	1	<	<	ζ	<	<	Windows - template powder coated (✓ or 🗙)
			NA	1	1	7	i	1		1	1	Į	1	1		Loft & Kitchen platform required ? (Yes or No)
			No	1	1	1	1	1	1	,		ļ	1	1	١	Loft & Kitchen platform provided (• or × or NA)
			1	>)	١	}	}	}	})	١)	١		Loft & Kitchen platform slope (v or X)

Quality Control Check Repot. Stage: After Brickwork (Apartments)