20)uality
327	nality Control Check Repot
Į	
	Stage: Before Casting Slab (Vi
	ing Slab (Villa)

j					
Block No	7.8	Slab No.	0	SI. No.	27143
Company	Nulyme & Hata Project		11/5mg est. 6	Phase	F]
Prepared by	P. 855 Kung		Pridy	Date	3/5/17
Project Manager		Sign	Red	Date 03 05/17	3/5/17
Previous stage report no.	U	26588	Report filed and signed by	d by PM?	QYes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointed ired.	ed only after recheck l QC report to QC team. l out in the QC report.	y QC. ATR not required.	

Slab Check. Notes:

- 1. Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 2. Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2") Show length and width of balconies (Tolerance 1") Show inner dimensions of ducts. (Tolerance 1") Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

	_	,		
Staircase slab thickness	Staircase width	Staircase - mid landing 2	Staircase - mid landing1	Slab Dimensions Check Plan enclosed?
Specified: 5"	Specified wd: 3.3"	Specified ht: 4, 3"	Specified ht: 4.3"	ed?
Actual: 5 u	Actual wd: 3! 3 "	Actual ht: 4! 311," Within	Actual ht: 4,3"	enclosed? \(\sqrt{Y}\text{Ycs} \text{No}
Within tolerance of 1/4"? Wes No	Specified wd: 3.3" Actual wd: 3.3" Within tolerance of 1/2"?	Within tolerance of 1/2"?	Specified ht: 4.3" Actual ht: 4.3" Within tolerance of 1/2"?	
Wes No	Yes No	√Yes □No	Yes No	-

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Ouality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good VAvg. Bad
18"extension to beam bottom runners on outer side provided?	☐Yes ☐No
Quality of Bracing Provided?	☐ Good [¬Avg. ☐ Bad
Alignment of beams on outer side?	Good Avg. Bad
Shuttering leveling?	☐ Good Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐ Correct ☐ Needs correction
Remarks:	

Slab Steel check, Notes

- Mark V for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:
	<	Steel check – slab extensions/ joints	16.
V.0 0	1	Steel check – floating columns	15.
		Electrical Conducting	14.
Good Ave Bad	<	Steel Check - Column steel overlapping length and cranking	
Good Avg Bad		Covering blocks for slab	12.
Cood Ava Bad		Steel Check - Slab Fxtra Bars	=
Cood NAve Bad		Steel Check Slab cranking & chairs	10
Cand Nave Bad		Steel Check - Slab spacing of bars	<u> </u>
Avir Bad		Steel Check - Slab size of bars	\$.
M Good Ave Bad		Depth and width of beams	7.
	<	Covering blocks for beams	6.
Good VAvg. Bad	<	Steel Check - Beams Bearing	5.
Good VAva Bad	\ <u>\</u>	Steel Check - Beams Overlapping & Cranking	4.
Cood Ave Rad		Steel Check - Beams Extra Bars	3.
- 11	<	Steel Check - Beam size of bars	2.
V Good Ave Bad		Steel Check - Beam no of rods	1.
(Good / Avg. / Bad)	(v or X)	Item	S No
Onalitative Check		Zumic) Zomo	