## ATR on Quality Control Check Repot. (Bungalows)

Bungalow No	45	QC report stage	and the second s	Sl. No.	21408
Company	Server Construction	Project	Soun turon	Phase	
Prepared by	٦	Sign	Spil John Source	Date	04-02-19
Project Manager	Soul and un Source	Sign	3	Date	
Receipt by OC date	0	Cian	0		04,000
Receipt by QC date	***	Sign		Other	
Receipt at HO date		Sign		Other	
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation that was made by QC:  Stop further work. Submit ATR on Q  Stop further work. Proceed with work.	ecommendation that was made by QC:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.	port to QC team. Proceer submitting ATR on	eed only after recheck l QC report to QC team.	by QC.	
Notes:					

## Notes:

- Attach a copy of the QC report to this sheet.

  Circle each correction with a red pen tick ( ) each circle for work completed and cross ( ) each circle where work has not been completed. Give remarks for each case where work has not completed on this sheet.

  Make 2 copied of the ATR send one to MD and other to QC.

- Enclose required photographs hard copy.

					Remarks:	
					ALL	
					paints	
					8	
					All paints on Bourted which is given by as	
					which	>
				0	is getuin	
	£.			C	Ex	
					000	
					The second secon	
_						

Subject: Cancell the ID no's-31498 & 31499 raised at Serene Farms Site. reg-

From: "QC" <qc@modiproperties.com>

Date: 18-09-2018 4:02 PM

To: "aruna" <aruna@modiproperties.com>

CC: "soham modi" <sohammodi@modiproperties.com>, "Ashaiya"

<ashaiya@modiproperties.com>, <serene@modiproperties.com>, "QC"

<qc@modiproperties.com>

To.

Aruna Madam.

Please Cancell the ID no's-31498 & 31499 raised for Villa no's-45 & 46 (After Electrical & Plumbing) QC Check at Serene Farms Site. Pending Works are as Below.

- Villa no-45 (After Electrical & Plumbing)
- In Toilets for Plumbing Lines(Holes) instead of Core-Cutting Machine they done by hand Chipping.
- (b) External Drainage Lines work also not Completed totally.
- √(c)) OHT's not Fitted.
- In Previous Stage QC Report(After Plastering) Corrections mentioned also not done like Junction Covers Finishings.
- ✓ ♠ At Set-backs Levell Marking with Blue Oxide not done.
- √ ⑤ Screeding in Toilets not done.
- (g) Plumbing Holes in Toilets not fixed with Cement-Mortar
  - 2) Villa no-46 After Electrical & Plumbing)
  - a) In Toilets for Plumbing Lines(Holes) instead of Core-Cutting Machine they done by hand Chipping.
  - b) External Drainage Lines work also not Completed totally.
  - c) OHT's not Fitted.
  - d) In Previous Stage QC Report(After Plastering) Corrections mentioned also not done like Junction Covers Finishings.
  - e) At Set-backs Levell Marking with Blue Oxide not done.
  - f) Screeding in Toilets not done.
  - g) Plumbing Holes in Toilets not fixed with Cement-Mortar.

At the Time of After Plastering QC Check all the Points were Explained to Site-Engineers Shiva and Sarvar also but they didnot Completed the Works. Send Self-Check Report to QC Team and again raise new QC Requests

Regards, QC Team.