Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Recommendation: Stop further work. Stop further work Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		no.	Radherbran	785 Jan Sign	Malano col te	961
eport to QC team. Proceed ter submitting ATR on sing corrections pointed ired.	MD Sign	27246	Sign	Sign Pala	Project	Slab No.
eed only after recheck l QC report to QC team I out in the QC report.		Report filed and signed by PM?	Report	18 6- FLAS	Hildma conte	7.0
by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	□Yes □No	Wes □No	41014	大三か カン	P	11242

Slab Check, Notes

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for easting.
 Prepare Slab Dimensions Check Plan as follows:

 Show outer dimensions of slab. (Tolerance 2")
 Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
 Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

4. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.	n colour. Circle each incorrect d	limension with red colour and	mention actual dimension next to	ıt.
Slab Dimensions Check Plan enclosed?		∏Yes □ No		
Staircase - mid landing1	Specified ht: 4.9"	Actual ht: 1/2 91/2	Actual ht: $\frac{1}{12} \cdot \frac{1}{41} \cdot \frac{1}{2}$ Within tolerance of $\frac{1}{2}$? \boxed{Y} es \boxed{N}	∵Xes
Staircase - mid landing 2	Specified ht: $\frac{1}{2}$, $\frac{1}{4}$	Actual ht: V. 911.	Actual ht: $\gamma \cdot q_{1!}$ Within tolerance of $\frac{1}{2}$? γ	√Yes ∐No
Staircase width	Specified wd: 3, 10	Actual wd: 3 . \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Specified wd: 3 10 Actual wd: 3 11 Within tolerance of 1/2"? Yes \(\text{No}\)	Yes No
Staircase slab thickness	Specified: 5-11	Actual: 5 "	Within tolerance of 1/4"?	√Yes ∐No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

- 1						_	5.00	1
	Remarks:	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Shuttering leveling?	Alignment of beams on outer side?	Quality of Bracing Provided?	18" extension to beam bottom runners on outer side provided?	Quality of centering, rod bending and concreting?	Quality of contents, for behalf and contreting.
		Correct Needs correction	☐ Good [] Avg. [] Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐Yes ☑No	Good Neg. Bad	

Slab Steel check. Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Remarks:	16.	15.	14.	13.	12.	Ξ.	Ξ	9,	8.	7.	6.	5.	4.	ω.	2.		S No
	Steel check slab extensions/ joints	Steel check – floating columns	Electrical Conducting	Steel Check - Column steel overlapping length and cranking	Covering blocks for slab	Steel Cheek - Slab Bxtra Bars	Steel Check Slab cranking & chairs	Steel Cheek - Slab spacing of bars	Steel Check - Slab size of bars	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
100 CO			<			V	<			V.	< .	<	<.	<	<	V	Quantitative Check (• or ×)
	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	✓ Good Avg. Bad	Good Avg. Bad	Good Avg. Bad	Good Avg. Bad	Good Avg. Bad	Good ☐ Avg. ☐ Bad	Good Avg. Bad	☐ Good [Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	☑ Good ☐ Avg. ☐ Bad	YGood ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)