Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR no	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No	
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making Proceed with further work. ATR not required	•		Radherbyen	Piszi Kunan	xlitom estate	65	
eport to QC team. Proceed teams of the submitting ATR on the corrections points of the corrections of th	MD Sign	2557)	Sign	Sign	Project	Other	
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.		Report filed and signed by PM	Robert	Par	Allows elble Phase		
by QC. ATR not required.	For filling	ed by PM	Date	Date	Phase	SI. No.	
	Yes No	YYes No	= = = = = = = = = = = = = = = = = = = =	こ(ヘニャ	(=)	としたと	

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided. Provide granite soffit for main door in this stage.

	Main door granite soffit workmanship Good Nvg Poor Main door granite soffit edge	Granite soffit for main door required Yes No —	Main door fixed with lock & stopper Yes No	Miscellaneous check.
(☐ Good ☐ Avg ☐ Poor	□Yes □No —	☐ Yes ☐ No	
polishing	Main door granite soffit edge	Granite soffit for main door provided		
C_s.COMM	Good Avg Poor	∐Yes ∐No		

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Miscellaneous check – after finishing stage II Quality and workmanship of portico tiles	Good VAvg. Poor
Quality and workmanship of flooring & setbacks	Good Avg. Popr
Quality and workmanship of external cladding/ texture	Good Avg. Poor
Remarks:	