## Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on MD Sign	26609	Project Manager A. Sunesh Sign	Prepared by S-SUM dilyman Sign	Company SVR Project	Villa No. +1 Stage	
seed only after recheck by QC.  1 QC report to QC team.  d out in the QC report. ATR not required.	For filling Yes No	Report filed and signed by PM?	Date 10(5)7	1005/14	VOC Phase	Si. No. 24169.	

### Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

### Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction

- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XX for major mistake that cannot be corrected.

  9"unplastered area from SFL should be left including in common areas and terraces.

  Windows must be checked with templates. Tolerance ¼".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Re	19	18	- C	17	16	15	14	ت ا	12		10	9	8	7	6		1	_	_	2	_	1000	No
Remarks	Other:	Ounty	Thilipp	Kitchen	Portico	Head room	Ferrace/balcony 2	Terrace / balcony 1	Lobby-2	Lobby-1	Dining	Drawing	Toilet 4	Bedroom-4	TOTIEL 2 1. C.		Redroom 3 V- Sec		m	Toilet 1 G. Tol	Bedroom 1 (xi) Deg	•	Room
				<u>-</u>	1	,	1	(	1	J	1	<	1		(		ζ	<	ς	(	, <		Skirting Provision ( v or x)
		-		(	1	1	5	<	1	j	1	<	.   !		1	(	5	ς	ς	<	,	5	Finishing around door frame ( v or X)
	-			5	,   1	1	(	, (	1	1	1	<	,		1	(	5	(	, ,	, ,	,		Beams & columns finishing (✓ or ×)
		_		1		- 		1 1		\ \	)	}	1	1	-	١	,	1 1	1	1		,	Finishing of lofts ( or ×)
			-	-		1	1	ς -	-	1	1		5	1	1	(	+		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		5	5	Electrical junctions finishing ( v or x)
				-	`\	!	1	(		1	1	1	5		1	<	<del> </del>	5	<	5	ς	5	Window check
				_	X	1	1	1	1	٦	,	1	-	1	1			]	<	1	(	1	Tiles provision ( • or ×)
					X		1	1	j	1	}	1	1			1	1	1	١	1	1	1	Sink provision & size
					(	-		-	5	1	1	1	(		1	1	ζ	5	(	3	(	, ,	Grooves for door frames ( v or x)
					1	-	-	  ×	×	1	1	1			1	١	١	5		1			Balcony & terrace silt top finishing 10 ( v or )
					1	1		1	1	1	1	1		•	<del>-</del>		1	1		1		1	Screeding in bathroo & utility ( v or x)
						)	1	)	)   :		!	3	3	)	,	)		)	ر ا ا		1	1	Screeding in 6" above FFL? ( or X)

Quality Control Check Repot. Stage: After Plastering (Villas)

# Quality Control Check Repot. Stage: After Plastering (Villas)

Remarks:	Plastering quality of paraper wans ( or x)  Plastering and finishing of chajjas ( or x)	Is plastering of compound wall and villa external walls 6" below FFL of Schools.	Plastering of compound wall & gate pillars (v or x)	Miscellaneous check Overall quality of plastering?
			rs? Yes No	☐Good ☐ Avg. ☐ Bad