## ATR on Quality Control Check Repot. (Apartments)

Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATP on QC report to QC.	MD Sign For filling		Project Manager ( Sign Date	S. Sowi) Kymy Sign Date	Project Visty Homes Phase	L ( oob to cop) QC report stage 6 SI. No.	
,	☐Yes ☐No		0	1618	1	30405	

- Notes: Attach a copy of the QC report to this sheet.

  Circle each correction with a red pen — tick ( ) each circle for work completed and cross ( ) each circle where work has not been completed. Give remarks for each case where work has not completed on this sheet.

  Make 2 copied of the ATR—send one to MD and other to QC. Enclose required photographs—hard copy.
- Remarks: