

Flat No	B-805	Other		SL No.	38457
Company	MPL	Project	MFP	Phase	-
Prepared by	T. Vinod Kumar	Sign		Date	25-09-21
Project Manager	Subba Reddy	Sign		Date	25-09-21
Previous stage report no.	37743			Report filed and signed by PM	☒ Yes ☐ No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No

Recommendation:

- ☐ Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- ☐ Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- ☒ Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- ☐ Proceed with further work. ATR not required.

Inspection should be done after :

- Completing stage II works.
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the QC report have been completed. Work can proceed to next stage.

Project in-charge	Sign	Date
		27/9/2021

Miscellaneous check:

Modular kitchen to be provided	☒ Yes ☐ No	Modular kitchen provided	☐ Yes ☒ No
Modular kitchen workman ship	☐ Good ☐ Avg ☐ Poor	Modular kitchen granite & dado workman ship & finishing	☐ Good ☐ Avg ☐ Poor
Video door phone /wifi cam to be provided	☒ Yes ☐ No	Video door phone/wifi cam provided	☐ Yes ☒ No
Painting marks and drops are cleaned from floor, windows, walls.	☐ Good ☒ Avg ☐ Poor		

Rate the quality of (Good ✓, Avg. ✕, Poor – needs correction ✕✕, NA)													
S No	Room	Door, door knob & door stopper fitting	Door, door knob & door stopper cleaning	Window grills & quality	Window grills fitting & finishing	Windows quality	Window fitting & finishing	Balcony railing quality & finishing	French door quality & fitting	CP jali quality and fitting	Edge building	Switch boards fitting & covering with plastic covers	Junction box covers painting
1	Bedroom 1- M.Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Bedroom 2 C.Bed	✓	✕	✓	✓	✓	✓	✓	✓	✓	✓	✕	✓
3	Bedroom 3 G.Bed	✓	✕	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Drawing	✕	✕	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Lobby 1- Poola	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility / balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Utility /balcony 2-	✓	✕	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	Utility / balcony 3-	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	Kitchen	✓	✓	✓	✓	✓	✕✕	✓	✓	✓	✓	✓	✓
11	Toilet 1- M.Toi	✓	✕	✓	✓	✓	✕	✓	✓	✓	✓	✓	✓
12	Toilet 2- C.Toi	✓	✕	✓	✓	✓	✕	✓	✓	✓	✓	✓	✓
13	Toilet 3- G.Toi	✓	✕	✓	✓	✓	✕	✓	✓	✓	✓	✓	✓
14	Other												
15	Other												

Remarks

Note: 1. Main door not locking properly.

2. In drawing room generated charge over not removed.

3. In utility grill not fixed.

4. In kitchen grill not fixed.

5. In kitchen seepage started.

Draft finishing..check.report.apts. stage III .dt 17-10-2020 ver5

6. For french door mosquito mesh not provided.