Remarks from site on the 'Requisition by Site Report' of purchase division

Company: Modi Re		alty Mallapur LLP		Date:		1	9.07.22				
		ar Residency		Prepared by:			Basaveshwari				
Report From / To 4.07.22 to					Approved by:						
Report Date 9.07.22 List of requisitions numbers missing in the repo											22426 193430
List of requi	sitions nu	mbers mis	sing in the repo	rt*: Req no	: 1932	15,193275,	19331	8,193	3356,193389,19	93390, 19	93426,193430
List of requi	sitions wi	nere PO/W	O not prepared	3 WORKIN	g days a	ner requisit	.1011.				
Req No.	Req Date		serial no of iteam in Req	of Item Description		ription	Reason for not preparing PO/WO				
193295	6.06.	22	1		Visiting cards		Promotion to follow up				
193346	18.06.22		1to 10	Channel bracket, Anchor bolt		Po to be issue.					
193392	28.06.22		1 to 10	Electrical wires		Po to be issue.					
193428	2.07.22		1	MS z angle templates		Po to be issue.					
193429			1,2	PVC u profile ,PVC false ceiling		Po to be issue.					
List of requi	sitions wh	nere PO/W	O is prepared a			been receiv	ed at s	site b	eyond the lead	time:	
Req No.			Serial no of item in Req.	Item Description		Details of discussion with supplier				supplier	
193159	5.05.22		1,2	Tan brown granite			Ready with supplier we arranging vehicle.				g vehicle.
193300	7.06.22		1	Glass balcony railing			Work in progress.				
193218	16.05.22		2	Pressure switch			Supplier did not get PO from purchase.				chase.
193361	22.06	5.22	22 1		Cp-pillar cock			No stock at SSLLP.			
193366	22.06	5.22	1	Tan bro	Tan brown granite		Ready with supplier we arranging vehicle.				
193368	22.06	5.22	1	Panel door		Ready with supplier we arranging vehicle.					
193374	22.06	5.22	1 to 10	Electrical wires		No stock at SSLLP.					
193376	22.06.22		1 ,5,7,8,9	Electrical wires		No stock at SSLLP.					
193398	29.06	5.22	1	False ceiling			Work in progress.				
193399	3399 29.06.22		1	False ceiling		Work in progress.					
193400	29.06.22		1 to 6	Panel doors		Ready with supplier we arranging vehicle.					
93406 30.06.22		1	False ceiling			Work in progress.					
193407 30.06.22		1	False ceiling			Work in progress.					
93414 1.07.22		4,7	Pillar c	Pillar cock, short body			No stock at SSLLP.				
193433	6.07.2	22	1	False c	eiling	-	Partly material will be received.				
No of gate passes issued this wea		ık	From No.		From No.	0.700		9735			
Delivery van	site visit	on:		5.07.22	2, 7.07.2	22, 9.07.22	1			1	
nward repor	t (MRN/o	ther) &sto	ock report ema	iled in pdf	format	to purchase	e			Yes	
tem not ord	ered but r	eceived : N	Vill								
etail of stee	& cemes	nt stools			1.00						
INO	Tor size		/t per mtr	W/4 C -							
		kgs		Wt. for 1: rod – kgs						Previous stock in kgs	
	8mm		0.395	4.74		102	7 7				
	10mm		0.617	7.		NILL		NILL			
1	12mm	1	0.888		10.6			2,32			1

4.	16mm	1.580	18.9	NILL	NILL		
5.	20mm	2.469 29.6		39	1154		
6.	25mm	3.86 46.32		48	2,223		
7.	32mm	66.67		NILL	NILL		
8.	Binding wire				125		
OPC stock	0	OPC last weeks stock	0	PPC/PSC 'stock	38	PPC/PSC last weeks stock	144
Details		Project Manage	er of K	Admin Officer/Manager		Admin Audit	
Sign		1 22		24/07/22			
Date			20/01	Odlo!!			

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks - For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!