## Modi Properties & Inv. Pvt. Ltd - Site Audit Report by Praveen

Company:		Modi Realty Miryalaguda	Date of site visit:	31.07.18 (Tuesday)			
Site:		AVR Gulmohar Homes	From / To time:	11:00 to 16:00			
Visited by:		Praveen	Prepared by: Praveen				
Other:					T		
Sl No.	Description			Remarks Yes			
1.		Is the 'Material shifting authorization forms' used at site?					
2.		Are the forms serial nos mentioned in the Hire charges register?  Is the 'Material issue authorization forms' used at site?					
۷.	Are the form's serial nos mentioned in the stock register?						
3.	Are the Site office, Clubhouse and Model Flats properly maintained and						
<i>J</i> .	cleaned on a daily basis?						
4.	Is Security properly dressed and are provided with a stick and torch? No.						
	of security personal as approved?						
5.	Is scrap properly arranged and sold as and when required?						
6.	Is the Creche running properly with midday meals?						
7.	Keys are properly labeled and numbered?						
8.				neat and	Na		
	Is use of helmets and safety belts properly enforced? Are 12 nos. neat and clean white helmets stocked at security cabin in apartment projects for						
	customers?						
9.	Is utility bills and payments details/register updated by Admin Officer						
	regularly?						
10.	Is the condition of labour quarters, water and sanitation facility in order?						
1.1	Is there misuse of electric power?						
11.	Are requisitions properly filed and signed by project manager?						
12.	Are attendance, building material, inward, hire charges, cement, outward,						
	electricity, etc., maintained properly and signed by engineer and admin						
13.	officer at site?  Do weekly reports tally with registers?  Yes						
	Do weekly reports tally with registers?				Yes		
14.	Are there any receipts of building material before 9 am and after 6 pm without due authorization?						
15.	Is job work register being properly maintained?				No		
16.	Is the attendance recorder properly installed and used? Is the ID no.				Yes		
10.	registered properly maintained?						
17.	Has security supervisor ensured that all vacant flats & villas are locked?				Na		
18.	Are gate passes being properly maintained and correctly filled?				Yes		
19.	Are Bills & Dc's Inward\outward register being properly maintained				Yes		
20.	Stores and stock registers are properly arranged / maintained?				Yes		
21.	Is the constructions circular spiral bound in good condition? Is file for						
	latest circulars and internal memos properly maintained?						
22.	Are hire charges and building material photographs being printed from						
	database within one working day?						
23.	Are store rooms properly secured?				Yes		
24.	There is no material lying outside the storerooms?			Yes			
25.	Stock Register quantity tallies with physical quantity?			Yes			

26.	Is turnkey contractor's material exchange log book maintaining properly?				
List of stores checked		Stores checked (Y /N)	Qualitative rating		
			(G/A/P)		
Electrical		Yes	Average		
Cement		Yes	Good		
Plumbi	ng – PVC	Yes	Average		
Plumbi	ng –GI	-	-		
Sanitar	<b>y</b>	-	-		
CP fitti	ngs	-	-		
Tiles		-	-		
Lift		-	-		
General	Material	Yes	Good		
Tools		Yes	Good		
Doors &	k hardware	-	-		
Misc.		-	-		

Remarks on default in following standard procedures: Nil

Remarks on corrections made in registers or database: Nil

## Complaints: Yes.

- 1. Building material and hire inwards are not authorized by Admin and PM on daily basis from 28.07.2018.
- 2. PO's & WO's are not enclosed for Req No 52349,52395, 52411 and 52406 after lead time.
- 3. Requisitions are not signed by Engineer/PM Req No 52425,52424,52423,52419,52416,52415, 52414 & 52417
- 4. Job work sheets are not signed by contractors, Sl.No 1934,1930,1924,1918,1921 & 1916
- 5. The following code rates to be updated in stock statement report. Code Nos: 2114,2370,2371,2372,2205,2211,2213,2214,4525,4620,4696,6031,6127,6610,10230,7 053,7123,7158,7328,7350,7351,7183,7265,7367,7287,11001,7529,7578,8014,8023,80 26,8069,8106,8184,8501,8529,9524,9501 and 9580.
- 6. Keys to be labeled properly as per advice.
- 7. Required to deploy 01 sweeper for maintain site office and model villa.
- 8. Assign one sub meter for office and model villa as per policy.
- 9. Minor error are solved at site same day.

## Suggestions:

- 1. Office staff members are not displaying their ID cards in office ours/site visit.
- 2. Office and stores to be re arrange properly.
- 3. There is an absent of creach teacher for four days.
- 4. Sweeper to be deploy for office and model villa purpose (Cleaning required).
- 5. Broadband, local person is ready to provide at site (site new office).