Company		MRGV	Audited by	B Lokesh ku	mar
Site		BRGV	Sign	Tokesii kulilar	
Project manager name		Sarwar	Date	19/06/2004	
Sign		Jul	Previous site visit date	05/04/2024	
AGH ma	Original copy of report + i by Lokesh atleast once a y be visited once in a mor d ATR within 3 days of th	th/quarter 6 Rating show	Ashaiya). 2. This report to be sent on site viber to se sent. 4. All other sites may be visited once in all be good, avg., poor. 7. In ATR required fill	group on same day.	3. All major sites to
Sl. No.	Description/con	Rating			
1.	Labour complia	+			
2.	Tying of safety	Avg			
3.	Material stored	Avg			
4.	Engineers aware	Good			
5.	Maintenance of	Good			
6.	Electrical power	Avg			
7.	Working of guar	Avg			
8.	Working of cam	Good			
9.		Avg			
10.	Maintenance of	Good			
S No.	Safety procedure	Avg			
	Suggested rectifi	cations/corrections	S		ATR required
2.					
3.					
l. No.	Suggested impro	vements in SOP (th	hat can be easily taken up)		
1.					
2.					
3.					
I. No.	Suggested improv Admin/Constructi				
1.		,			
2.					
3.					

EHS Audit - Site Visit Report

Con	npany	MHPL SOV	Audited by	B.Lokesh Kuman	
Site	1 -	SOV-III	Sign		
Project manager name		K.Purshotham	Date	21-05-24	
Sign		W	Previous site visit date	20-05-24	
visited may b	J L. I aleach atleast once a week	and this report to be sent. of the control of the c	ya). 2. This report to be sent on siteviber g 4. All other sites may be visited once in to 1, avg., poor. 7. In ATR required fill Yes/	vo weeks. 5. Sites like	Serene and AGH
SI. N	o. Description/comp	liance with safety procedures			Rating
1. Labour compliance		e with PPE			Good
		s wherever required.			Good
Material stored saf		ely and properly.			Good
4.			with safety procedures includ	fety procedures including their PPE.	
5.	Maintenance of labour quarters, cleanliness, provision of toilets & water supply.		Good		
6.	Electrical power supply for construction activity, pumps, temporary lighting.			Avg	
7.	Working of guard siren.		Good		
8.	Working of cameras + power supply to cameras.		Good		
9.	Maintenance of creche, creche teacher, mid-day meals.		Good		
10.	Safety procedures for earth work including earth storage, barricading, shoring.		Good		
S No.	Suggested rectificat			ATR required	
1.	Suggested rectificat	ions/corrections			
2.					
3.					
	0 . 1:				
No.	Suggested improven	nents in SOP (that	can be easily taken up)		
1.					E. BERREY
2.					
3.					
	 Suggested improvements in SOP (to be implemented after discussion with Admin/Construction Team/Etc.) 		ion with MD/		
1.					
2.					
			ROSE CONTRACTOR OF THE PROPERTY OF THE PROPERT		Cally Dunie at Discourse