

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No.


Date : 19-1-2022

Activity : Part - Driveway slab

(South west - of B (Sole - A)

checked slitting reinforcement and observations are as follows.

- 1) Bent or cut the terminated column reinforcement
- 2) provide chairs
- 3) provide corner stirrups
- 4) check all support - thoroughly and provide extra support wherever required
- 5) provide bracing both directions & two level



6) Grade of concrete is 20 (1:1.5:3) M. & 12mm dia bars

- 7) curing shall be done 21 days
- 8) de-slitting shall be done after 14 days
- 9) leave work for further execution.

Engineer Sign.

Date :

Consultant Sign.

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818


Sl. No. **1051**

Date : 19.1.2022

Address: Totil Col - slab and beam
(Between Block 4 and 5)

chuland shuttering, reinforcement and
specification are as follows

- 1) provide ~~down~~ dowels
both slab and beam for further extension
- 2) provide corner bars.
- 3) provide chairs



- 4) Leave dowels both slab and beam for further extension.
- 5) Grade of concrete shall be allowed
- 6) check all supports
- 7) Curing shall be done 22 days
- 8) De shuttering shall be done after 14 days

Engineer Sign.

Date :

Consultant Sign.

19/1/2022
C. S. R. S. R.

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

1052

Sl. No.

Date : 27-1-2022

Activity: Part - 7th slab of Block-C
(Flat 502, 503, 504, 505, 506
+ Condo)

checked shuttering, reinforcement and
observations are as follows.

- 1) provide addl. chairs
- 2) provide column development bars
- 3) Seal all minor openings
- * 4) Leave doneb for further extensions.
- 5) check all supports
- 6) Grade of wire R20 (1:1½:3) up. shall be allowed
- 7) Curup shall be done 21 days
- 8) De shuttering shall be done after 14 days

* Safety : Take all safety measures

Engineer Sign.

Date :

[Signature]

Consultant Sign.

Date :

[Signature]
27/1/2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1053**

Date : 27/1/2022


Activity: To level slab of Block H

checked shutter reinforcement and observations are as follows.

1) provide chains under cracked Rebar



2) Leave dowels for further extension as follows.



Not vertical. leave Horizontal

3) Seal all minor openings

4) provide eduction development bar

5) check all supports

6) clean rubbish on shutter

7) Crimp shall be done 24 days

8) All shutter shall be done after 14 days

Engineer Sign.

V. Seibath

Date :

Consultant Sign.

Date :

27/1/2022
GIRI/24/5/2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1054**

Date : 28/1/2022

Activity : 8th slab of Block-G

checked shuttering, reinforcement and observation are as follows :

- 1) provide chains
 - 2) break the reinforcement of column reinforcement in the slab.
 - 3) provide column development bar to staircase head room and lift columns.
 - 4) check all supports
 - 5) seal all minor openings
 - 6) width of void 120 shall be allowed.
 - 7) curing shall be done 21 days
 - 8) de shuttering shall be done after 14 days
- note: follow all safety measures

Engineer Sign. K. Srikanth

Consultant Sign.

Date : 28/01/2022

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818


Sl. No. **1055**

Date : 11/2/2022

Accessing : part - Int. Driveway of Block E
(North side)

checked structure over front and
observation are as follows

- 1) Leave down both slab and beams for
further extension.
- 2) Remove outside. and place sides to get
8" thick slab.
- 3) Check all supports
- 4) DBR, DBR, DBR top edge and 2-20% slab of
H_y.
- 5) Grade of soil up to 20 shall be allowed
- 6) curb shall be done 2 days
- 7) All of structure shall be done after 14 days



Engineer Sign.

Date :

G. Raju
01/02/2022.

Consultant Sign.

Date

G. Raju
11/2/2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1056**

Date : 1/2/2022

Address: Part - 8th & 2nd & 3rd floor - 4
(Flats 602, 603, 604, 605)

checked & verified meticulously and
observations are as follows.

- 1) provide addl. charges
- 2) Break the reinforcement of terminated column
in the slab
- 3) Seal all minor openings
- 4) Check all dampness
- 5) Concrete & air dry shall be allowed
- 6) Cracks shall be done re doing
- 7) All checks shall be done after 14 days

Engineer Sign

Date :

G. Jayu
4/2/2022

Consultant Sign.

Date :

1/2/2022
Siraj

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. 1057

Date: 4-2-2022

Activity: 6th slab of Club House

checked shuttering, reinforcement and
observations are as follows.

1) provide addl. chairs under cracked reinforcement

2) seal all minor openings.


3) provide column development bars.

4) place cover slabs between and bottom of beams

5) check all supports

* 6) provide slugging along tie beams @ corners
other wire mesh deployed to working personnel.

7) grade of min M20 (1:1 1/2:3) MP
shall be all over



8) curing shall be done 21 days

9) de shuttering shall be done after 14 days

R. S. Sathya
Engineer Sign.

Date: 4/02/2022

Consultant Sign.

Date: 4/2/2022

Giri / 20/12/2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. 1058

Date: 1/2/2022

Address: Park 7 to Kalyan Block-C
(Plot 501, and 507)

checked slotted, reinforcement and
observations as follows

1) provide column development bars

2) provide chairs

3) check all supports

4) Concrete of mix ratio shall be allowed

5) curing shall be done as per

6) cover slotted shall be done after curing

Engineer Sign.

Date:

M. S.

Consultant Sign.

Date:

1/2/2022
M. S.

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551


GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818


Sl. No. **1059**

Date : 1/2/2022

Remarks: column shifted 3rd away
from original position @ Block H
Grid: B.3 column



Shift and location in the plan



Engineer Sign.

Date :

G. Jay
01/02/22

Consultant Sign.

Date :

SECTION

1/2/2022
Girish

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1060**

Date : 22-2-2022

Activity : Part- 2nd slab of Block- H. (~~part-1~~)

checked & kept up requirement and observations
are as follow

1) Provide column development bars

2) Provide chair

3) place cover blocks.

4) Seal all minor opening

5) leave dowels both slab/ Beams for further extension

6) check all supports

7) Casting shall be done 22 days

8) De shuttering shall be done after 14 days

Engineer Sign.

Date :

[Signature]
22/02/2022.

Consultant Sign.

Date :

[Signature]
22/2/2022
Girip/2022/2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

GULMOHAR RESIDENCY

5-4-1873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1061**

Date: 13/3/22

Address: Paul - 8th Ward of Kolle - C
(Plot No 602, 603, 604, 605
and 606)

checked & verified, measured and observation
are as follows

1) Plot - is like 8x40 top - culture 2m 89, 100 are
interlocked masonry

2) Provide chain



3) Provide chain development 5m to 8m in core head Kan
culture and left culture 0.147

4) Seal all masonry openings

5) Check all supports

6) Provide 2 wire mesh slab to all roads

7) Cracks & cracks to done 2 days

8) Use of chain wall to done after 14 days

9) Leave done for further extension.

Engineer Sign.

[Signature]

Date:

11/3/22

Consultant Sign.

[Signature]

Date:

11/3/2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-18/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1062**

Date : 9/5/2022

Subject: Pedersen Rd Dist. Line A to Chikla
checked & nothing was found and
situation was found.

- 1) Please Heavily pad along suspension and
- 2) provide chain
- 3) Underpass 2-200 or top below E.C.B.
- 4) check all respond
- 5) fill the tunnel above overpass
- 6) provide wire 1/20 & fill to all over
- 7) ~~the~~ Casing & fill to be done in days
- 8) the sludge shall be done after 14 days

Engineer Sign.

Consultant Sign.

Date :

Date :

9/5/2022
Sunil Kumar

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-1873&4, II Floor, M.G. Road,

Secunderabad - 500 003.

Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,

Hyderabad - 500 076.

Phone : +91 91210 21818

Sl. No. **1063**

Date : 9/5/2022

Address: Raamp Chow 11th 105-3rd

checking & taking, sea front,
and observation are as follows

- 1) provide chain
- 2) place corner stone,
- 3) leave done for further extension &
that level (11-6)
- 4) level of air to wall is all over
- 5) check all supports
- 6) confirm wall before always
- 7) the building shall be done after 15 days

Engineer Sign.

Date :

9/5/2022
Consultant Sign.

Date :

9/5/2022
9/5/2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4, 187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1064**

Date : 9/5/2022

Address: Andhaly Block-H

checked 11/2/2022. No objection any
speculations are as follows.

- 1) provide chain
- 2) provide cover story
- 3) Seal all minor openings
- 4) provide closure development being
- 5) provided air H2O shall be ~~also~~ allowed

6) Check all supply

7) c/wp shall be done 2 days

8) the stitching shall be done after 10 days


11/2

Engineer Sign.

Date :

Consultant Sign.

Date :


9/5/2022
2022/5/9

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. 1065

Date : 2/6/2022

Activity: Part- 7th slab of Club House

checked shuttering, reinforcement and ~~beams~~ are as follows


1) provide addl. chairs



2) provide column development bars

3) check all supports

4) provide bracing



5) Seal all minor openings

6) Cracks & air voids shall be allowed

7) Curing shall be done 21 days

8) Re Shuttering shall be done after 14 days

Engineer Sign.

Date :

2/6/22

Consultant Sign.

Date :

2/6/2022
Girish (Signature)

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1066**

Date : 2/6/2022

Address : Paul- 3rd slab & Block-H
(Plot 103, 104, and 105)

checked shuttering, reinforcement and observations
are as follows

- 1) Side shuttering is complete as per new
- 2) provide chairs
- 3) provide column development bars
- 4) seal all minor openings
- 5) Leave down for further extension & consider
- 6) check all supports
- 7) curing shall be done 21 days
- 8) Deck shuttering shall be done after 14 days

Engineer Sign.

Date :

02/06/2022

Consultant Sign.

Date :

2/6/2022
Girish [Signature]

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY


Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1067**

Date : 21/6/2022

Activity : Part- podium slab of Block C
(@ 105 level)

checked shuttering, reinforcement and
specifications are as follows


- 1) B7, B7, B7, B7 - top and bottom 1-25 p missing
- 2) provide chairs, 
- 3) Check all supports -
- 4) Leave down both slab and beams for further
examination
- 5) Seal all minor openings
- 6) provide additional bars
- 7) Crisp shall be done 2 days
- 8) We shutter shall be done after 14 days

Engineer Sign.

Date :

Consultant Sign.

Date :


21/6/2022
Gurav/24/25 JSL

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. 1068

Date : 21/6/2022

Address: Bottom slab of O.H.T-2 of
Block-C

checked shuttering reinforcement
and specifications are as follows

- 1) provide chairs
- 2) check all supports
- 3) Seal all minor openings
- 4) ~~check~~ provide vertical and dist bars
- 5) curing shall be done 2 days
- 6) de shuttering shall be done after 14 days

Engineer Sign.

Date :

Consultant Sign.

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1069**


Date : 25-6-2022

Activity : Pour- of the slabs of Block-H


(Floors : 203, 204, 205 + Corridor)

checked shuttering, reinforcement and observations are
as follows.

- 1) provide addl. chairs
- 2) provide corner stirrups
- 3) provide Column development bars
- 4) check all supports
- ★ 5) Leave dowels, both slab and beams for further extension along corridor
- 6) curing shall be done 28 days
- 7) de-shuttering shall be done after 14 days
- ★ 8) Follow all safety norms


Engineer Sign.

Date : 25/6/22


Consultant Sign.
Giri/20.05.2022
Date : 25/6-2022

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1070**

Date : 7-7-2022


Activity: part- 2nd Drive way slab
of Block-C

checked shuttering, reinforcement and
observations are as follows

- 
- 1) clean rubbish, dead mortar @ column and beam junctions.
 - 2) Bent the reinforcement of terminated column in the slab.
 - 3) Mastered Missip along expansion joint
 - 4) check all supports
 - 5) provide bracing both directions
 - 6) Grade of air or so shall be allowed.
 - 7) Curing shall be done 2 days
 - 8) De shuttering shall be done after 14 days


Engineer Sign.

Date :


7/7/2022
Consultant Sign.

Consultant Sign.

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY


Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1071**

Date : 21/7/2022

Action : Pal- Ist- Driveway slab of
Block-c

checked shuttering reinforcement and
observations are as follows.

- 1) Place corner bolts.
- 2) provide chairs ~~at~~ B12- level same as in
miss copy @ top level.
- 3) provide column development bar
- 4) Has to be ensure free of slab/beam
for proper bonding
- 5) check all support 
- 6) provide bracing to the dwellers
- 7) Curis shall be done 22 days
- 8) de shuttering shall be done after 14 days

Engineer Sign.

Consultant Sign.

Date :

Date :


21/7/2022
Crm/2022/5 Adh

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. 1072

Date : 27-8-2022

Activity : Part - 2nd Dremeway slab
of Block - c

checked shuttering, reinforcement and
observations are as follows

- 1) provide chairs
- 2) provide corner bolts
- 3) Bent / cut - the terminated column need joint
- 4) check all supports
- 5) Hack the one step face of slab / beams
- 6) clean rubbish inside shuttering
- 7) Grade of air or 20 shall be allowed
- 8) Cure shall be done 21 days
- 9) Wash shuttering shall be done after 14 days

Engineer Sign.

Date :

Consultant Sign.

Date :

27/8/2022
GIRI 2095 Sub

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818


Sl. No. **1073**

Date : 3/9/2022

Activity : 8th slab of club house

checked shuttering, reinforcement and stationary areas follow

- 1) provide Addl. chairs
- 2) cut the reinforcement of terminated columns.
- 3) provide column development bars to stair case and lift columns
- 4) Seal all minor openings
- 5) check all supports
- 6) provide bracing both direction @ 3 levels.
- 7) Baffle prop the slugging
- 8) Curved of min H₂O shall be allowed
- 9) curp shall be done 21 days
- 10) De shuttering shall be done after 14 days



[Signature]
Engineer Sign.

Date : 3/9/22

[Signature]
3/9/2022
Consultant Sign.

Date :

Date: 7/24/03

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-18/73&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1075**

Date : 19-10-2022

Activity : Post- Possession Visit 2nd floor
(11th-6th) level

checked shutters, reinforcement and observations
are as follows

1) Make the window frame of beams/slabs for
proper bonding

2) provide chairs

3) check all keepers

4) provide bracing @ two level

5) Curved of wire too shall be allowed

6) Crisp shall be done at least

7) Be & bracing shall be done after 14 days

Engineer Sign.

Date :

Consultant Sign.

Date : 19/10/2022
GIRI NATS & SONS

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-18/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1076**

Date : **8/2/2023**

Activity : Paul 3rd Drive away walls
with masonry blocks 'H' and clad them
choked shutter reinforcement and
observation areas follows.

1) Bidm Gulmohar has made the masonry on either side

2) provide chains 

3) Made the shutter wall for masonry on clay

4) Choked masonry

5) Seal all minor openings


6) Made a mix 1:1:6 shall be all over

7) masonry shall be done as follows

8) The shutter shall be done after 14 days

9) leave down joints and masonry finished extension

Engineer Sign

Date : 

Consultant Sign


Date **08/02/2023**
5/2/2023

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-1873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1077**

Date : 2/3/2023

Activity : Paint E-F Drive way slab
(44 Blue and steel trowel)

checked thoroughly, measurements and observations
are as follows.

1) Provide chairs - 

2) Provide charmer development bar

3) Cracked is about 4 or 5 mm slab.

4) Top surface has missing one grid.

5) Leave slabs for future extension.

6) Check as supports

7) Curved of size 1:12:13) up. Slab will be all over

8) Curved shall be done 21 days

9) Be slabs shall be done after 14 days




2/3/2023

Engineer Sign.


Gul Mohar Residency
Consultant Sign.

Date : 2/3/23

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-1873&4, II Floor, M.G. Road,

Secunderabad - 500 003.

Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19 Mallapur,

Hyderabad - 500 076.

Phone : +91 91210 21818

Sl. No. **1078**

Date: 14-3-2023

Address: Paur Talab Dine camp
(Plot No. 11 and Block-11)

checked & satisfactory and
observations are as follows

1) Provide chain 

2) Provide column development bar

3) Seal all minor openings

4) Check all supports

5) Leave slowly both sides and breezy for further
extension

6) Grade of air fire shall be allowed

7) Crust shall be done as days

8) The & battery shall be done after 14 days

Engineer Sign.

Date: 14/3/23

Consultant Sign.

Date:

14/3/2023
Gite / 2023/05/24

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

#5-4-1873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1079**

Date : 27-3-2023

Admitty: Part - I & II (Pedicor)
Indelover B. Reddy H and Subhanya
checked structure, neighbour and observation
are as follows

- 1) Looked the missing slab/ beams and columns
- 2) Clean subsoil on slab structure
- 3) Provide column development bars
- 4) Check all supports
- 5) Grade of mix M20 shall be all over
- 6) curing shall be done 21 days
- 7) The plastering shall be done after 14 days

Engineer Sign.

[Signature]
27/03/23

Consultant Sign.

[Signature]
27/03/2023

Date :

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/2&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY


Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1080**

Date : 31/3/2023

Remarks : Drive way slab / Roofs
(Substandard slab above 3rd flr. & below)

Looked the missing concrete / not
Mechanic done.

Issue :  Drill & look out - with
proper done and
live



Issue : 

Drill off.
direction
and overlay

 Crack done

Engineer Sign.

Consultant Sign.

Date :

live welding
shall be done


Date : 31/3/2023
Cmr / Data's Arch

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1081**

Date : 8/5/2023

Activity : Paint and Plastering

Gate/door & 4" Stone-paved stone

checked shuttering, reinforcement and dimensions
are as follows:-

- 1) Trade prepared curing paper & slab/beam
- 2) provided chairs
- 3) Seal all minor openings
- 4) checked all supports
- 5) provided min 12% shall be allowed
- 6) leave done's with slab/beam further extension
- 7) curing shall be done 7 days
- 8) the shuttering shall be done after 14 days

Handwritten Signature
8/5/2023

Handwritten Signature
8/5/2023

Handwritten Signature
8/5/2023

Engineer Sign.

Consultant Sign.

Date :

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-1873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551


GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1082**

Date: **26/7/2023**

Address: Kamepp (1st - 8th to 2nd slab)



Look at channel Helling or EDS Road Don'ts marking

Engineer Sign.

[Signature]

Consultant Sign.

[Signature] **26/7/2023**

[Signature] **26/7/2023**

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

GULMOHAR RESIDENCY

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1083**

Date: 1/9/2023

Activity: Part - 2nd Floor (Top 4th) & all
and across (nuclear H and G Stone).

checked quality, coefficient and dimensions
are as follow

1) Provide chain 

2) Provide concrete Slabs.

3) Grout / cast terminated columns near ground

4) Check all supports

5) Clean wall with on slab & floor

6) Curing of air H no shall be allowed

7) Curing shall be done 21 days

8) De dusting shall be done after 14 days

Engineer Sign. 

Consultant Sign.

Date: 1/9/23

Date: 1/9/2023


Gul/20/2023

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-1873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY


Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1084**

Date : _____

Activity 1 Excavation for Swimming Pool

1. From FFL excavate 6' depth for main pool & 3'6" depth for kids pool. (Excavation 2' extra from all side)
2. After excavation do manual leveling of the excavated area.
3. Lay 6" R.C.C bed on the excavated area.
4. Mark the exact pool dimension & shape.
5. Make a single brick marking.
- * R.C.C wall 8" thickness for swimming pool & balancing tank.



Engineer Sign.

Consultant Sign.

Date :

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-41873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1085**

Date : _____

6. Bottom steel mat 6" c/c 10mm Tn botways,
(single mat) & along with R.C.C wall reinforcement.
7. Filter pipe line laying

→ Balancing Tank & Filter Area.

1. Excavation 7' from FFL of 8'x8' dimension.
2. Lay 6" R.C.C bed. Top of R.C.C from FFL 6'6".
3. Provide steel mat 10mm Tm @ 6" c/c.

Engineer Sign.

Date :

Consultant Sign.

Date :


11/6/23

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

GULMOHAR RESIDENCY

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1086**

Date : 14-9-2023

Address: Raamp (105' hnd to 95' hnd)

(Near club house)

checked & everything, neediness and observations
are as follows.

1) provide addl. chairs

2) F/C taken from right below the screen
level (highly objectionable).

3) Grade of soil also should be allowed

4) hole set - wiring down. for screen/slab

5) work should be done 21 days

6) Be & latching should be done after 14 days


Engineer Sign.

Date : 14/9/2023


Consultant Sign

Date :

14/9/2023
Gireesh Reddy

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1087**

Date : 18-10-2023

Adenatop: Raff-reinforcement and Chlorine

of Blue-VE.

checked thoroughly, reinforcement and
staircases, are as follows-

- 1) provide addl. Churn cuts as per
- 2) Side & interior in complete manner
- 3) please see concrete bottom and side
- 4) Cracks & void shall be allowed in floor slabs


18/10/2023

18/10/2023

Engineer Sign. 

Consultant Sign.

Date : 18/10/23

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551


GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1088**

Date : 23-12-2023

Attended: Foundation & / Rcdle Stake-Net
indications of Blmle-E



Engineer Sign.

(Signature)

Consultant Sign.

Date :

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1089**

Date : 20/11/2024

Attny: Peddica Reddy Renu-3

checked drafting, measurement
execution as per plan

1) provide chairs



2) provide columns as per plan - being

3) check all supports

4) grade of m/c shall be as per plan

5) comp shall be done as per plan

6) the drafting shall be done as per plan

7) leave done both end/beam for future columns

Engineer Sign.

[Signature]
20/11/24

Date :

Consultant Sign.

[Signature]
20/11/2024

Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1090**

Date : 5-2-2024

Address: 1: Part 'O' Land Slab & Bldgs-3
Address 2: Part 'R' Slab & Bldgs-3

checked cladding, roofing and foundation
are as follows

- 1) Provide drains
- 2) Provide column development bars
- 3) Leave doors for slab & beams for future entrance
- 4) Cladding not done properly ~~1~~ ~~2~~ ~~3~~
- 5) Check all supports
- 6) Cracks in masonry shall be allowed
- 7) Roof shall be done as per drawing
- 8) The cladding shall be done after 14 days

Engineer Sign.

Date : 5/2/24

Consultant Sign.

Date : 5/2/2024
Gireesh Kumar Singh

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

GULMOHAR RESIDENCY

5-4-1873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No.

1091

Date : 29/3/2024

Attained 1: Part 1st & 2nd (Dine wing)
between 3rd & 4th

Attained 2: Part 2nd Dine Hall &
(Western side)

checked & nothing, nevertheless an observation
are as follows:

1) Provide chairs

2) Apply nitro bond / cement slurry while
concreting

3) Check all supports

4) Check of air etc shall be allowed

5) Curing shall be done 21 days

6) The shuttering shall be done after 14 days

Engineer Sign

Date : 29/3/24

Consultant Sign.

Date: 29/3/2024
GIVE DATE & SIGN

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1092**

Date: **25-5-2024**


Address: Panch 3rd & 4th of Kotha is
(Plot 101, 102, 103, 107)

checked & further inspection and
observation are as follows

- 1) provide addl. chain 1-11-1
- 2) Not-to-encroach adme boundary lines
- 3) provide clear development - bus
- 4) chalk all boundary
- 5) provide of wire mesh shall be allowed
- 6) wiring shall be done at deep
- 7) the 8 butterfly shall be done after 14 days

Engineer Sign.

Date:


25/5/24

Consultant Sign.

Date:


25/5/24
Gireesh Reddy

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-1873&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1093**

Date : 24-6-2024

Activity: Paving of the Road of Block - E
(Plotted 20, 202, 206, 207)
checked & nothing significant was observed
one as follows

- 1) Provide chains
- 2) Provide column development - bars
- 3) Seal all minor openings
- 4) Check all supports
- 5) Grade of mix also should be allowed
- 6) curing should be done 21 days
- 7) See & nothing should be done after 14 days

Engineer Sign.

Date :

Consultant Sign.

Date :

24/6/2024
24/6/2024
Gireesh Kumar

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1094**

Date : 9/8/2024

Address: Park - 6 Vasthaly Dorek-E
(Plot 304)

checked & verified roof frame and structural
are as follows

1) Provide chains



2) Provide cover slabs

3) Provide edge beam development bar

4) checked supports

5) curing shall be done 28 days

6) Use of chalking shall be done after 14 days

Engineer Sign.

Date :

Date :

Consultant Sign.

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1095**

Date : 22/8/2024

Attny: Paul B to Shashikala E
C Flats. 1, 2, 6, 7)
checked to the, verified and observations
are as follows

- 1) Provide chairs IL
- 2) Provide cleaner development - 500
- 3) Seal all window opening
- 4) Check all support
- 5) Provide of air to be allowed
- 6) Roof shall be done at least
- 7) Dewatering shall be done after the work

Engineer Sign.

Date :

Consultant Sign.

22/8/2024
Date :

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1096**

Date : 21/9/2024

Activity: Drive way slab 2C level 114.60

(between Block-F and Block-C)

checked & with self, reinforcement and
observation are as follows

1) Reinforcement is as per drawing

2) Adequate self-reinforcing beams and slab (as per drawing)

3) Hade the face of beams and slabs [17.17]

4) Check all supports

5) Leave drawing for further reference.

6) Grade of mix must be as per drawing

7) Work shall be done as per drawing

8) Be careful shall be done after 14 days.

Engineer Sign.

Consultant Sign.

Date :

Date :

21/9/2024

21/9/2024