EHS Audit - Site Visit Report

Company		MHPL SOV	Audited by	Lokesh	
Site		SOV-III	Sign	TRAGE	4
Project manager name		K.Purshotham	Date	04-10-24	
Sign		1	Previous site visit date 02-08-24		The second second
be visit	ted by Lokesh atleast once a	week and this report to be sen ath/quarter. 6. Rating should be	ya). 2. This report to be sent on site vib it. 4. All other sites may be visited once e good, avg., poor. 7. In ATR required	e in two weeks. 5. Sites i	like Serene and
A STATE OF THE PROPERTY OF THE		apliance with safety procedures			Rating
1. Labour complia		nce with PPE			Avg
		nets wherever required.			Good
3.	Material stored safely and properly.		Good		
4.	Engineers awareness and compliance with safety procedures including their PPE.		Good		
5.	Maintenance of labour quarters, cleanliness, provision of toilets & water supply.		Good		
6.	Electrical power supply for construction activity, pumps, temporary lighting.				Good
7.	Working of guard siren.		Good		
8.	Working of cameras + power supply to cameras.		Avg		
9.	Maintenance of creche, creche teacher, mid-day meals.		Good		
10.	Safety procedures for earth work including earth storage, barricading, shoring.		Good		
No.	Suggested rectifications/corrections		ATR required		
DB boxes need to fix properly					
2. Repair guard sin				The second	
3.	Repair guard siren	115/11			
No.	Suggested improve	ements in SOP (that	can be easily taken up)		
	Suggested improve	oments in 501 (izza			
.					
	G	ments in SOP (to be	implemented after discus	sion with MD/	
No. S	Suggested improvements in SOP (to be implemented after discussion with MI Admin/Construction Team/Etc.)				
101					

EHS Audit - Site Visit Report

Company		GVRC	Audited by	B Lokesh kur	nar
Site		INNOPOLIS	Sign	01-10-2024	
Project manager name		T Madhu	Date	K. Codust	
Sign		Mallur	Previous site visit date		
be visit	ted by Lokesh atleast once a	week and this report to be ser th/quarter. 6. Rating should be	ya). 2. This report to be sent on site viber it 4. All other sites may be visited once it e good, avg., poor. 7. In ATR required fil	n two weeks. 5. Sites	s like Serene and
		pliance with safety procedures			Rating
Labour compliance		nce with PPE	with PPE		
2.	Tying of safety n	Good			
3.	Material stored s	Good			
4.	Engineers awarer	Good			
5.	Maintenance of la	Good			
6.	Electrical power s	Avg			
7.	Working of guard siren.				Good
8.	Working of camer	Avg			
9.	Maintenance of cr	Good			
10.	Safety procedures	Good			
No.	Suggested rectifications/corrections				ATR required
1.	DP boxes are need				
2.	3600 block safety i				
3.	10. 10. 10. 10. 10. 10. 10. 10. 10. 10.				
lo.	Suggested improve				
.					
o. S	uggested improven dmin/Construction	nents in SOP (to be in Team/Etc.)	implemented after discussion	n with MD/	