EHS Audit - Site Visit Report

Company		MHPL SOV	Audited by	B.Lokesh		
Site		SOV-III	Sign	131-6	M	
Project manager name		K.Purshotham	Date	28-02-25	-	
Sign	low	5	Previous audit date			
AGH may	by Lokesh atteast once in a mod ATR within 3 days of t	a week and this report to be set onth/quarter. 6. Rating should be this report.	ya). 2. This report to be sent on site ont. 4. All other sites may be visited to be good, avg., poor. 7. In ATR requirements.	nce in two weeks 5 Sites	like Serene and manager/Engineer	
1.	Description/compliance with safety procedures Labour compliance with PPE				Rating	
2.	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER,	Good				
3.	Tying of safety	Avg				
	Material stored	Good				
4.	Engineers awa	Good				
5.	Maintenance o	Avg				
6.	Electrical power	Good				
7.	Working of gu	Good				
8.	Working of car	Good				
9.	Maintenance of	Good				
10.	Safety procedu	Good				
S No.	Suggested rectifications/corrections					
1.	Need to maintain labour quarters neat & clean					
2.						
3.						
l. No.	Suggested impr					
1.						
2.						
3.						
l. No.	Suggested impro					
_	Admin/Construc	ction Team/Etc.)				
1.						
2.						
3.						



EHS Audit - Site Visit Report

Company		NOH	Audited by	B Lokesh Ku	mar		
Site		NGH	Sign	mk	mkd		
Project manager name		Vijay raj	Date	28-42-2025	28-42-2025		
Sign		II	Previous site visit of				
ACH may	by Lokesh at least once	a week and this report to be oth/quarter_6_Rating should	haiya). 2. This report to be sent on site sent. 4. All other sites may be visited of the good, avg., poor. 7. In ATR require	sace in two weeks. 5. Site	es like Serene and		
SL No.		Rating					
1.	Labour compliance with PPE Avg						
2.	Tying of safety	Avg					
3.	Material stored	Good					
4.	Engineers awar	Avg					
5.	Maintenance of	Good					
6.	Electrical power	Avg					
7.	Working of gua	Good					
8.	Working of can	Avg					
9.	Maintenance of	Good					
10.	Safety procedur	Good					
S No.	Suggested rectif	ATR require					
1.	Safety nets need						
2.	Cleaning required in multiple areas						
3.	Electrical wires joints is there in multiple areas and DP Boxes are not fixed properly						
I. No.	Suggested impro	ovements in SOP (tha	at can be easily taken up)				
1.							
2.							
3.							
II. No.	Suggested impro Admin/Construc						
1.			-, -				
2.							
3.							

