

**MODI REALTY MALLAPUR LLP**

# 5-4-187/3&4, II Floor, M.G. Road,  
Secunderabad - 500 003.  
Phone : +91 - 40 - 66335551

**GULMOHAR RESIDENCY**

Sy. No. 19, Mallapur,  
Hyderabad - 500 076.  
Phone : +91 91210 21818

Sl. No. **1010**Date: 27/12/2019

Inspection of concrete (R.C.C.) work surrounding service  
lift 3. 'A' Block


→ Anchor bolts provided around the around the  
lift periphery.

→ Provide distribution steel to the anchored  
downs.


→ Fabricate foundation mat 8mm @ 6" c/c both ways  
where ~~not~~ <sup>is</sup> foundation resting on soil.

→ the depth of concrete around the periphery  
shall be 1 1/2" (min.).

→ Complete the fabrication work instructed  
above and then pour concrete. The grade of  
concrete shall be M 20.

  
Engineer Sign.

Date: 27/12/19

  
Consultant Sign.  
Zaid & Associates  
Date: 27/12/2019