

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1018**Date : 07-02-2020

Inspection of first slab above A' between the grid
B-N/5-10. Beams & slab Reinforcement &c
Satisfactory.

- ① Check revised drawings replace beam B3
with B32 @ grid A & D.
- ② Beams & slabs reinforcement other than
above are correct & as per structural
details.
- ③ Provide dowels for beams & slabs near
construction joints as per structural drawings.
- ④ Check all construction joints apply bonding
chemical & proceed concrete pouring.

Engineer Sign.

Date :

07/02/2020

Consultant Sign.

Date : 07/02/2020