

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1020**

Date : 07.03.2020

① Inspection of 2nd slab of lower B Flat Nos 2 & 7.
beams & slab reinforcement & shuttering.

- Beams & slab reinforcement checked found correct as per (structural) drawings
- Close all shuttering gaps & then pour concrete.

② First slab - Staircase & landing near of lower A.

- All top & bottom steel of beams shall be anchored using in existing structure.
drill 6"-8" holes apply Locofix or Hilti-Reson chemical to fix rods.
- Complete all the work & re check the slab.

Engineer Sign.

Date : 07/03/2020

Consultant Sign.

Mohammed Ashendlin

Date : 20/03/2020