

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1021**

Date : 14/03/2020

① Inspection of Second Slab of House 'A' flat NO. 3, 4, & 7
Beams & Slabs reinforcement & Shuttering.

→ Beam B9 reinforcement in flat '6' is not
as per the drawing. Replace / fabricate beam as per
the revised structural drawings.


→ Beams & Slabs reinforcement other than B9
is correct & as per structural drawings.

→ Provide additional supports with sufficient bracing
& rectify B9 & Pour concrete.


② Inspection of third Slab House 'B' flat NO
1 & 8.

→ Beams & Slab reinforcement checked found
correct as per structural drawings.

→ Close all shuttering gaps & then pour
concrete.


Engineer Sign.

Date : 14/03/2020


Consultant Sign.

Muhammad Ashimuddin
Date : 14/03/2020