

aruna@modiproperties.com

From: <sohammodi@modiproperties.com>
 Date: 30-10-2018 8:03 AM
 To: <aruna@modiproperties.com>
 Attach: V.no-79 slab-02.jpg; V.no-56 Col-1.jpg; V.no-57 slab-1.jpg; V.no-71 col-1.jpg; V.no-72 PB.jpg
 Subject: FW: Curing not happening at SOV Site. reg-

Aruna,

Print

Regards,

Soham Modi

Managing Director | +91 40 6633 5556 | sohammodi@modiproperties.com
 Don't just buy a flat / villa! Buy a great lifestyle!
 Affordable flats / villas in gated communities.
 Modi Properties Pvt. Ltd. | www.modiproperties.com
 5-4-187/ 3 & 4, M G Road, Sec'bad -03 | Ph: +91 40 6633 5551

From: QC <qc@modiproperties.com>
 Sent: 29 10 2018 04:37 PM
 To: soham modi <sohammodi@modiproperties.com>
 Cc: QC <qc@modiproperties.com>
 Subject: Curing not happening at SOV Site. reg-

To,

Soham Sir.

As we went today for QC Check at SOV Site, so we have observed that Curing was not happening upto 21 Days.

The Villa no's and Slab Casted Date's are as follows-

- 1) Villa no-79 (Slab-02) this Slab was Casted on =23-10-2018.
- 2) Villa no-57 (Slab-01) this Slab was Casted on =24-10-2018.
- 3) Villa no-71 (Col-01) this Slab was Casted on = 25-10-2018.
- 4) Villa no-72 (Plinthbeam) this was Casted on = 26-10-18.
- 5) Villa no-56 (Col-01) this was Casted on = 19-10-18

Note: 1) Concern Engineer- Veerabrahmam not seeing whether Curing happening Regularly or not and they are doing Curing only at the time of Curing Photos sending to QC.

- 2) Simply raising QC Requests (RCC) by listening Contractor's Words and not even making Self-Check.
- 3) As We already explained to Project Manager a number of times regarding Veerabramam Works at Site, But again doing same mistakes without seeing any Works just raising the Requests.

Please find the photo copies also.

Regards,
 QC Team.

30-10-2018

