

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551


GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818


Sl. No. **1022**Date : 27/05/2020

Inspection of driveway slab: between block in
2nd slab - Beam & Slab reinforcement
& chipping.

- length of extra bottom reinforcement slab is
shorter than required.
- cranking of slab reinforcement needs to be
rectified to attain a slab thickness of 8".
- Provide extension bars in slabs & beams
@ construction joint
- Rectify the length of extra bars (bottoms)
- Rectify above points inform after
rectification and pour concrete


27/05/2020
Engineer Sign.

Date :


Consultant Sign.

Date : 28/05/2020