

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.
Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.
Phone : +91 91210 21818

Sl. No. **1023**


Date : 02/06/2020

Inspection of 2nd slab of Block D Flat No
1, 2829 - Beam & slab reinforcement & shuttering

— ~~Beam & slab~~ Beam & slab reinforcement
should follow layout & as per structural
drawings.

— Provide column tie or beam through at
beam column junctions -

— Close all shuttering gaps & then
pour concrete.



Engineer Sign.

for Ramana / Sir Puri

Date :

2/06/2020

Mohammed Arshad
Consultant Sign.

Zamil & Associates

Date : 02/06/2020.