

CONSULTANT INSPECTION REPORT

MODI REALTY MALLAPUR LLP

5-4-187/3&4, II Floor, M.G. Road,
Secunderabad - 500 003.

Phone : +91 - 40 - 66335551

GULMOHAR RESIDENCY

Sy. No. 19, Mallapur,
Hyderabad - 500 076.

Phone : +91 91210 21818

Sl. No. **1024**

Date : **08/06/2020**

Inspection of Slab & Flat No. 5. Beam & Slab reinforcement & Shuttering.

→ 1-12mm extra top reinforcement in BB is missing. Provide 12mm bar as per details

→ Provide chair & cover blocks under reinforcement.

→ Provide extension bar / hook for Slab/beam when Slab & beam are continuous beyond construction joints of Slab & beam in slab. Rectify above points and then proceed for concrete pouring.

Engineer Sign.

Date :

08/06/2020

Consultant Sign

Date :

Mohammed Arshad
24/06/2020