Remarks from site on the 'Requisition by Site Report' of purchase division

		Aedis	Aedis Developers LLP		Date:		06.06.2020			
		MGA	MGA		Prepared by:		Priyanka	riyanka		
Report From / To 30.0		30.05	05.2020 to 05.06.2020		Approved by:					
Report Date 06.0		06.06	.2020							
List of requis	itions n	umbers	missing in the rep	ort*:						
					ring days after requ	isition:				
Req No.	No. Req Date		J		em Description	Reason for not preparing PO/WO				
100143 02.06.		6.2020		Ma	Main door beeding		PO prepared on monday			
					s have not been rec	eived at s	site beyond th	ne lead	l time:	
100130	11.05.2020		SI	Sliding Windows		Ready with Supplier				
	-									
					1 1					
No. of gate passes issued this v		s week:	1	From No.	1351	To N	0.	1351		
Delivery van				1st						
Inward report	t (MRN	/other)	& stock report em	ailed in p	df format to purcha	ase?	Yes			
DC register Sl. No. during the week From				m No.	10364		To No.		10364	
Items not ord	ered bu	t receiv	ed: Nil							
Items sent to	HO /ve	ndor tha	at are pending for	repair: Ni	1					
Other correct										
Details		Project Manager		Admin Officer/Manager		Admin Audit				
Sign			824'		poings					
Date			06.06.2020		06.06.2020					

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!