

aruna@modiproperties.com

From: <sohammodi@modiproperties.com>
Date: 22-04-2019 5:53 PM
To: <aruna@modiproperties.com>
Attach: NE_SouthSide Compound wall_Marking.pdf
Subject: FW: South side Compound wall sliding report

Aruna,

Print

Regards,

Soham Modi

Managing Director | +91 40 6633 5556 | sohammodi@modiproperties.com

Don't just buy a flat / villa! Buy a great lifestyle!

Affordable flats / villas in gated communities.

Modi Properties Pvt. Ltd. | www.modiproperties.com

5-4-187/ 3 & 4, M G Road, Sec'bad -03 | Ph: +91 40 6633 5551

From: Nilgiri Estates <nilgiriestate@modiproperties.com>

Sent: 22 04 2019 05:39 PM

To: Soham Modi <sohammodi@modiproperties.com>; Ashaiya <ashaiya@modiproperties.com>

Cc: Madhusudhan Eng <madhusudhan@modiproperties.com>; Srinivasa Kumar <srinivasakumar@modiproperties.com>

Subject: South side Compound wall sliding report

Respected MD sir,

As per your task, we marked wall sliding values on South Side compound wall from tot lot to transformer area. Please find the attached drawing. We found there is no plinth beam in bottom of the wall. And RCC columns are placed at every 45'. Remaining are brick pillars.

Regards,

G Srinivasa Kumar


Project Manager | +91 96403 83162 | srinivasakumar@modiproperties.com

Modi Properties Pvt. Ltd. | www.modiproperties.com

5-4-187/ 3 & 4, M G Road, Secunderabad - 03 | +91 40 66335551

Don't just buy a flat or villa! Buy a great lifestyle!

We build affordable flats & villas in gated communities.



Promoted by
 Adi Properties &
 Placement of Sou estments Pvt. L.
 ne: +01