

Errors in Drawings at AGH Site. reg-

Wednesday, 20 Sep 2017, 1:01 pm

To: acad.mppl@gmail.com

From: QC <qc@modiproperties.com>

Cc: agh <agh@modiproperties.com>, QC <qc@modiproperties.com>, suman kumar <suman@modiproperties.com>

To,

MD Sir

This is for your Kind Information that we went for QC Checking today for Plinth Beam(Type-AA2) we Observed that there are Errors in the Plinth Beam Drawings at AGH Site. But Work happened as per Correct Dimensions only, Hence we are attaching the Photo Copies of Drawings

The Errors are as Follows:-

a) In Type-AA1 at one place instead of **PB2=6"X15"**, But in Drawing it is mentioned as PB2=6"X12"

b) In Type-AA2 at Two places instead of **PB2=6"X15"**, But in Drawing it is mentioned as PB2=6"X12"

c) In Type-AA2 at one place instead of **PB1=6"X12"**, But in Drawing it is mentioned as PB1=6"X15"

Thanking You

Regards  
QC Team.