

QC - Concrete Cube Testing Report.																
Company:		SOVLLP														
Project:		SOV														
Report for Month:		Sep&Oct-20														
Prepared By:		QC Team														
Date:		13-11-2020														

7344	06-09-2020	RMC	M20	Scpl		115	Plinth		14-9-20	8	14.0	320.0	14.2		
											14.0	320.0	14.2	14.3	
											14.0	325.0	14.4		
7344	06-09-2020	RMC	M20	Scpl		115	Plinth		5-10-20	29	20.0	470.0	20.9		
											20.0	470.0	20.9	20.8	
											20.0	465.0	20.7		
7345	07-09-2020	RMC	M20	RCPL		102	Plinth		14-9-20	7	14.0	320.0	14.2		
											14.0	315.0	14.0	14.2	
											14.0	325.0	14.4		
7345	07-09-2020	RMC	M20	RCPL		102	Plinth		5-10-20	28	20.0	465.0	20.7		
											20.0	465.0	20.7	20.6	
											20.0	460.0	20.4		
7346	07-09-2020	RMC	M20	RCPL		119	Footings		14-9-20	7	14.0	320.0	14.2		
											14.0	325.0	14.4	14.4	
											14.0	330.0	14.7		
7346	07-09-2020	RMC	M20	RCPL		119	Footings		5-10-20	28	20.0	465.0	20.7		
											20.0	470.0	20.9	20.9	
											20.0	475.0	21.1		
7347	08-09-2020	RMC	M25	SCPL		131	Col	1	15-9-20	7	17.5	395.0	17.6		
											17.5	405.0	18.0	17.8	
											17.5	400.0	17.8		
7347	08-09-2020	RMC	M25	SCPL		131	Col	1	7-10-20	29	25.0	575.0	25.6		
											25.0	585.0	26.0	25.7	
											25.0	575.0	25.6		
7348	08-09-2020	RMC	M20	SCPL		127	Slab	1	15-9-20	7	14.0	320.0	14.2		
											14.0	325.0	14.4	14.4	
											14.0	325.0	14.4		
7348	08-09-2020	RMC	M20	SCPL		127	Slab	1	7-10-20	29	20.0	465.0	20.7		
											20.0	470.0	20.9	20.8	
											20.0	470.0	20.9		
7349	09-09-2020	RMC	M25	SCPL		126	Col	1	15-9-20	6	17.5	395.0	17.6		
											17.5	400.0	17.8	17.7	
											17.5	400.0	17.8		
7349	09-09-2020	RMC	M25	SCPL		126	Col	1	7-10-20	28	25.0	575.0	25.6		
											25.0	575.0	25.6	25.5	
											25.0	570.0	25.3		

7350	09-09-2020	RMC	M20	SCPL		122	Footings		15-9-20	6	14.0	320.0	14.2		
											14.0	325.0	14.4	14.3	
											14.0	320.0	14.2		
7350	09-09-2020	RMC	M20	SCPL		122	Footings		7-10-20	28	20.0	465.0	20.7		
											20.0	465.0	20.7	20.7	
											20.0	470.0	20.9		
7351	10-09-2020	RMC	M20	RCPL		117	Footings		18-9-20	8	14.0	325.0	14.4		
											14.0	330.0	14.7	14.5	
											14.0	325.0	14.4		
7351	10-09-2020	RMC	M20	RCPL		117	Footings		9-10-20	29	20.0	470.0	20.9		
											20.0	480.0	21.3	21.1	
											20.0	475.0	21.1		
7352	11-09-2020	RMC	M20	RCPL		104	Plinth		18-9-20	7	14.0	315.0	14.0		
											14.0	320.0	14.2	14.2	
											14.0	325.0	14.4		
7352	11-09-2020	RMC	M20	RCPL		104	Plinth		9-10-20	28	20.0	465.0	20.7		
											20.0	460.0	20.4	20.5	
											20.0	460.0	20.4		
7353	11-09-2020	RMC	M20	RCPL		105	Plinth		18-9-20	7	14.0	325.0	14.4		
											14.0	320.0	14.2	14.3	
											14.0	320.0	14.2		
7353	11-09-2020	RMC	M20	RCPL		105	Plinth		9-10-20	28	20.0	470.0	20.9		
											20.0	465.0	20.7	20.7	
											20.0	465.0	20.7		
7354	12-09-2020	RMC	M20	RCPL		106	Plinth		18-9-20	6	14.0	315.0	14.0		
											14.0	320.0	14.2	14.2	
											14.0	325.0	14.4		
7354	12-09-2020	RMC	M20	RCPL		106	Plinth		9-10-20	27	20.0	465.0	20.7		
											20.0	465.0	20.7	20.5	
											20.0	455.0	20.2		
7355	14-09-2020	RMC	M25	RCPL		101	Col	1	21-9-20	7	17.5	395.0	17.6		
											17.5	405.0	18.0	17.8	
											17.5	400.0	17.8		
7355	14-09-2020	RMC	M25	RCPL		101	Col	1	13-10-20	29	25.0	575.0	25.6		
											25.0	580.0	25.8	25.6	
											25.0	570.0	25.3		
7356	14-09-2020	RMC	M25	RCPL		102	Col	1	21-9-20	7	17.5	415.0	18.4		
											17.5	400.0	17.8	18.1	
											17.5	410.0	18.2		
7356	14-09-2020	RMC	M25	RCPL		102	Col	1	13-10-20	29	25.0	585.0	26.0		
											25.0	585.0	26.0	26.1	
											25.0	590.0	26.2		

