

MPL site Audit report dtd 21.01.2021 - reg

Yahoo Mail/Sent

**Ravi** <ravi@modiproperties.com>

Jan 21 at 5:40 PM

To: report-audit@modipropertis.com, report-audit@modipropertis.com

Cc: Soham Modi <sohammodi@modiproperties.com>, Praveen Audit <praveen@modiproperties.com>, Jai Kumar. G. <jaikumar@modiproperties.com>, Balakrishna Vista <balakrishna@modiproperties.com>, Ashaiya . <ashaiya@modiproperties.com> [more...](#)

To,
MD sir,

Please find the attachment of MPL site Audit report dtd 21.01.2021.

And the following other errors are found at site (Photographs are enclosed).

- 1) Labourers are not following safety measures (No helmets, Masks & Safety belts).
- 2) Workers children's are roaming at site.
- 3) Copper wire using to machineries instead of service wire.
- 4) Labourer bathrooms cleaning required.
- 5) 01 No's C.C camera is not working at north east side.
- 6) Bhavana House keeping staff (Office boy & Sweeper) is not wearing uniform on daily basis.
- 7) Labour quarters inside to be clean on weekly basis with bleaching powder.

Regards,

V.Ravi
Admin Manager -Audit | +91 95022 11011 | ravi@modiproperties.com
Modi Properties Pvt. Ltd. | www.modiproperties.com
5-4-187/ 3 & 4, M G Road, Secunderabad – 03 |
Don't just buy a flat or villa! Buy a great lifestyle!
We build affordable flats & villas in gated communities

5 Files | 895.4kB

**MPL- Audit report dtd 21-01-2021 (Team B)_docx.pdf**

26kB

**creche.jpg**

224kB

**copper wires.jpg**

200kB

**rcc labour.jpg**

240kB

**crech.jpg**

205kB