Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after su Proceed with further work only after making of Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager Zoul's Hoyam Sign	Prepared by 7. Vin and Kumen	Company	Villa No 8 U
scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	MD Sign	S7353 Report filed and signed by	Sign	Sign In June Kumal	Project AUR Culpan	Other
by QC. a. ATR not required.	For filling	ed by PM	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	Yes No	05-05-21	05-05-21	1	37606

Inspection should be done after:

- Completing stage II works.
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

MISCELIALICOUS CHCCN.		76 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Modular kitchen to be provided	Yes VNo	Modular kitchen provided	Yes No
Modular kitchen workman ship	Good Avg Poor	☐ Good ☐ Avg ☐ Poor Modular kitchen granite & dado	Good Avg Poor
	1	workman ship & finishing	1
Video door phone/ wifi cam to be	Yes □No	Video door phone/ wifi cam	☐ Yes ✓ No
provided	•	provided	

	Ren	15	14	13	12	11	10	9	8	7	6	5	4	ယ	2	_	S No	
	Remarks	Other	Portico	Toilet 3	Toilet 2 - C . Toi	Toilet - M: 701	Kitchen	Utility / balcony 3	Utility / baleony 2-	Utility / balcony 1	Lobby 1 - Pula	Dining	Drawing	Bedroom 3	Bedroom 2 C. Bed	Bedroom + M. Be	Room	
Meny				1	<	<u> </u>	1	١	1	<	1	١	<	1	<	<	Door, door knob & door stopper fitting	
2	_			1	<	<	1	1	1	<	1	1	<	1	<	`	Door, door knob & door stopper cleaning	
000	1			1	<	<	<	1	1	1	1	1	<	1	<	<	Window grills & quality	Rate the c
par	0			1	<	<	<	Ì	1	1	1	1	<	١	×	<	Window grills fitting & finishing	Rate the quality of (Good
	7			1	<	<	<	1	1	1	1	1	<	1	<	<	Windows quality	(Good 🗸
] -			Ĺ	<	<	×	1	1		1	1		1	<	<u></u>	Window fitting & finishing	, Avg.
Q				1	1	١	١	1	1	١	,	١	1	1	1	1	Balcony railing quality & finishing	X, Poor-
Cick	190			1	1	1	1	1	1	1	١	١	١	1		1	French door quality& fitting	
	*			1	<	<	. 1	1	1	*	1	١	1	1		1	CP jali quality and fitting	needs correction XX, NA)
				1	<	<	<	1	1	<	<	<	<	.	<	<	Edge building	X
				1	<		\ <u>\</u>	1	1	<	. <	<	`<	.	<		Switch boards fitting & covering with plastic covers	NA)
				1	<	<	<	. 1	1	<		<	<	1	<	<	Junction box covers painting	

Quality Control Check Repot.

Stage: After Finishing Stage III (Villas)

Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Miscellaneous check – after finishing stage III	
Quality and workmanship of gate	☐ Good ☑ Avg ☐ Poor
Quality and workmanship of railings	☐ Good ☑ Avg ☐ Poor
Painting of gates & railings	☐ Good Avg ☐ Poor
Cleaning, painting of external cladding/texture	☐ Good ☑ Avg ☐ Poor
Hole packing on external surfaces is in order	☐ Good ☑ Avg ☐ Poor
Layout of CPVC & PVC is in order	☐ Good ☑ Avg ☐ Poor
Use of fastners and clips for CPVC & PVC pipes is in order	☐ Good ✓ Avg ☐ Poor
Painting marks and drops are cleaned from floor, windows, walls, portico, setback	☐ Good ✓ Avg ☐ Poor
Correct quality of workmanship of lawn to levelling and compaction for lawn 6" below lawn FFL	Good Avg Poor
Remarks: Note: - Lawn not bid.	